

Reilley - DNR, Robin < robin.reilley@state.co.us>

## Review\_DMRS-2023\_Q4 Yoast and Seneca

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Fri, Feb 16, 2024 at 3:47 PM

To: "Kawcak, Miranda" < MKawcak@peabodyenergy.com>, Robin Reilley - DNR < robin.reilley@state.co.us>

Good Afternoon Miranda,

Please find DRMS's review of the above mentioned compliance reports for the Yoast and Seneca IIW mines. No concerns were noted.

## Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567 ext 8105 | F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

## 2 attachments



DMRReview\_Yoast\_2023\_Q4.docx 225K



16 February 2024

Miranda Kawcak Environmental Manger Peabody, Colorado Operations

Re: Yoast Mine (Permit No. C1994082) Review DMRs 2023 Q4

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2023 quarter four DMR reports for the Yoast Mine. The report covers the time period from 1 October through 31 December 2023. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 1 February 2024. Seneca Property LLC submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Yoast ponds sampled for DMRs comprise: Ponds 10, 11, 12, 13 and 14. Ponds 10, 12 discharged during the quarter. No exceedances were noted.

Seneca Properties submits the DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii), specifically within 30 days of sampling. The report is in compliance with the applicable sections of the Rule.

The Division has no further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP

**Environmental Protection Specialist II** 

Robin.reilley@state.co.us

