

Annual Report of

Conditions: M-2000-035

LEGEND

PERMIT BOUNDARY

EXIST. CONTOUR

BNDRY, DISTURBED AREA

DIRECTION OF MINING

PROPERTY LINE

MONUMENTED BNDRY


5/8" REBAR



100' 100' in feet



EXPIRED 10-16-00



Actual Disturbed area

Topsoil Berm w/ Temporary seeding

Stabilized Shale Pile

Mining Notes

Active operations ceased in July 2000

Mining shall begin at the site of the exit

CONTRACT

DATE