

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review DMRs 2024 March

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Thu, May 2, 2024 at 2:22 PM To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Mr. Roberts,

Please find the Divisions' Review of the 2024 March DMRs for Trapper Mine. The DMR report included WET testing results. No concerns were noted.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

P 303.866.3567 ext 8105 | F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us

Review_DMR_2024_03March_Trapper.pdf 267K



Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

2 May 2024

Re: Trapper Mine (Permit No. C1981-010) Review of DMR's 2024 March

Dear Mr. Roberts:

The Division has received and reviewed the March 2024 monthly Discharge Monitoring Reports (DMRs), including the acute WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 22 April 2024. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in February.

- o Johnson System Pond #10, NPDS 001
- No Name Pond #5 NPDES 002
- East Pyeatt #2
- Middle Flume #20

Trapper reported that none of the outfalls requiring WET testing discharged. Monthly DMRs for discharging outfalls indicated that no parameters were exceeded.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP Environmental Protection Specialist II Robin.reilley@state.co.us