

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review DMRs 2024 April Trapper

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us> Tue, May 28, 2024 at 10:36 AM To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Morning Graham,


Please find DRMS's review of the 2024 April DMRs for Trapper Mine. The Division has no concerns.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567 ext 8105 | F 303.832.8106 Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 robin.reilley@state.co.us | http://mining.state.co.us





Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

28 May 2024

Re: Trapper Mine (Permit No. C1981-010) Review of DMR's 2024 April

Dear Mr. Roberts:

The Division has received and reviewed the April 2024 monthly Discharge Monitoring Reports (DMRs), including the acute WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 17 May 2024. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported the following outfalls discharged in April.

- o Johnson System Pond #10, NPDS 001
- No Name Pond #5 NPDES 002
- East Pyeatt #2
- Middle Flume #20
- East Middle Flume #21

Trapper reported that none of the outfalls requiring acute monthly WET testing discharged. Monthly DMRs for discharging outfalls indicated that no parameters were exceeded.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Bobin Keiller

Robin Reilley, M.S. GISP Environmental Protection Specialist II Robin.reilley@state.co.us

