

COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

General Information

Disclaimer

Under the terms of your NOI and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following fee is due for the following NOI(s) on or before the Anniversary date:

Select Permit Number *

Only Permit Numbers with currently due Annual Reports and Fees will be listed. If nothing appears in the dropdown box below, there are no annual fees or reports due for any of your permits.

P1995013

Select Anniversary Date *

08-09-2024

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee *

I understand and agree to the terms

General Information			
Permittee Name			
Operation Name Iowa Mill Site			
Permit Number	Annual Fee Due	Permit Acreage	
P1995013	86.00	0.90	
County	Anniversary Date	Current Bond Amount	
Summit	08-09-2024	2000.00	
Proceed			

Contact Info

Here is the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information at the bottom of this page. Indicating that it is inaccurate will send an e-mail to notify your administrator to make the appropriate changes.

Permittee Contact Information

Permittee Contact Na Randall Stone	me				
Permittee Company lowa Milling Corp					
Permittee Address 1 4278 Garland St					
Permittee Address 2					
Permittee City	Permittee State	Permittee Zip			
Wheatridge	CO	800330000			
Permittee Phone #	Permittee F	ax #			
3039067371					
Permittee Contact Email Address advoc8e@GMAIL.COM					
Permitting Co	ntact Info				
Permitting Contact Na Anna Bengtson	ame				
Permitting Company White River National Fore	est - DIllon Ranger Dist.				
Permitting Address 1 680 Blue River Pkwy.					
Permitting Address 2					
Permitting City	Permitting State	Permitting Zip			
Silverthorne	CO	804980000			
	Permitting I				

Permitting Contact Email Address

Inspection Co	ontact Info				
Inspection Contact Name Randall Stone Inspection Company					
	4278 Garland St				
Inspection Address 2	2				
Inspection City	Inspection State	Inspection Zip			
Wheatridge	CO	800330000			
Inspection Phone #	Inspection F	ax #			
3034214375					
Inspection Contact E	mail Address				
Is the contact inform receive an email noti		: is not correct your organization's Administrator will			
		is not correct your organization's Administrator will			
receive an email noti		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			
receive an email notin • Yes No		: is not correct your organization's Administrator will			

Annual Report Questions

Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the affected area boundary clearly marked if you have an excavation or portal? *

● Yes ● No ● N/A

2. Is the site in final reclamation? *

```
🔘 Yes 💿 No
```

Please note time limits related to completion of reclamation, Rule 3.1.3.

3. Please enter the date of last activity at the site (excavation, drilling, construction). Or, if activity has not yet begun, please indicate so.*

No activity yet
Yes, activity has begun 9/18/2023

4. What date did prospecting activity end, or what date is it expected to end? Rule 5.6.1(e). * 10/1/2028

For the following questions, please note that numeric values must include one decimal place, such as "0.0" for zero acres, or 10.2 instead of 10.23.

5. Number of acres currently affected (exploration+ incomplete reclamation). ***** (?) 0.2

6. Number of acres that were newly affected during the current report year. * (?)0.0

7. Number of acres that were reclaimed during the current report year. ***** (?) 0.0

8. Estimated new acreage to be affected in the next report year. ***** (?) 0.0

9. Estimated acres to be reclaimed in the next report year. ***** (?) 0.0

10. Total acres in various stages of reclamation, since permitted exploration / prospecting activities began:

Total acres backfilled * (?) 0.0 Total acres graded * (?) 0.1 Total acres seeded with approved mix * (?) 0.1 Seed Application Method * Broadcast seeding Total acres fertilized with aproved fertilizer * (?) 0.0

```
Total acres with topsoil replaced * (?)
0.0
Total acres mulched with approved mulch * (?)
0.1
Mulch application rate (tons/ac) * (?)
0.0
Previous Proceed
```

Annual Report Questions

11. Is weed control being conducted in accordance with an approved Weed Control Plan? *

If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.

🔘 Yes 🔵 No 💿 <mark>NA</mark>

12. Is adequate topsoil reserved for reclamation, based on your approved NOI?*

If "NO", please explain Yes No No

13. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? *

If "NO", please explain

🔵 Yes 🔵 No 💿 <mark>NA</mark>

14. If exploration/prospecting has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? *

🔘 Yes 🔵 No 💿 NA

15. Are all hazardous materials stored within approved spill containment structures? *

○ Yes ○ No ● NA

16. Does your NOI reclamation plan or Environmental Protection Plan require you to submit monitoring information annually? *

🔘 Yes 🔵 No 💿 <mark>NA</mark>

17. As required by Rule 5.6(1)(g) confirm that the Financial Warranty is still in place and is adequate to fully reclaim the approved prospecting site disturbance(s). *

● Yes ○ No ○ NA

18. Please use the space below to describe as required by Rule 5.6(1)(c) any new prospecting activity that occurred during the preceding year, including the locations and number of new surface drill holes, mud pits, excavations, rock dumps, adits, shafts, trenches, pits, roads and structures. If applicable, you must also describe the measures taken to safeguard shafts, adits and other mine openings from unauthorized entry both during and after prospecting. Additional pages should be attached if needed.

Prospecting is done both surface/subsurface by sampling. Mine building is a locked temporary shed. The adit is locked by 2 hooded locks on a steel grate. Access to trestle is blocked by a wood barricade and sign. There is a hooded locked gate on the road to the mine. Mine and building maintenance and ventilation is ongoing. Warning signs are posted.

MAX 1500 Characters

19. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S.34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 5-11. *

Only PDF formatted files can be uploaded.

Carbonate Mine Iowa Mill.pdf

1.14MB

20. Rule 5.7 requires submittal of final abandonment reports within 60 days for any drill hole(s) with artesian flows and no later than 12 months for all other completed drill holes. If drill holes are a component of your exploration/prospecting activities, have they been properly abandoned? *

🔵 Yes 🔵 No 💿 <mark>NA</mark>

21. If you have supplemental information you would like to provide, please upload it here.

Only PDF formatted files can be uploaded.

Previous	Proceed
----------	---------

Annual Fee Payment

Payment Confirmation Number * (?)

231262272

Signature

Submittal Date

7/1/2024

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. *

I Agree

If you do not see the "Submit" button after completing your report, try to un-check and then re-check the "I Agree" box.

Previous