

Reilley - DNR, Robin <robin.reilley@state.co.us>

Review Q2 DMRs and Sed Pond reports

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Aug 7, 2024 at 12:16 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good afternoon Miranda,

Please find the above mentioned review for 2024 Q2 Seneca IIW mine site. DRMS has no concerns at this time.

Please let me know of any questions you may have.

Thank you

Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567| F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us

2 attachments



Review_Ponds_2024_Q2_Seneca.pdf



7 August 2024

Miranda Kawcak Environmental Manger Peabody, Colorado Operations

Re: Yoast Mine(Permit No. C1994082)

Review DMRs 2024 Q2

Dear Ms. Kawcak:

Thank you for your timely submittal of the 2024 quarter two DMR reports for the Yoast Mine. The report covers the time period from 1 April through 30 June 2024. The Colorado Division of Reclamation, Mining and Safety (The Division) received the above referenced reports on 5 August 2024. Seneca Property LLC submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Yoast ponds sampled for DMRs comprise: Ponds 10, 11, 12, 13 and 14. All ponds discharged during the quarter. No exceedances were noted.

The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP

Environmental Protection Specialist II

Robin.reilley@state.co.us

