

Notes:

9. No new area was disturbed this year. Mining was done on the west side in previously stripped areas to rebuild the stockpiles of pit run material. When more processed material is needed, mining will resume in the stripped and partially mined area shown on the map.

10. No reclamation is required at this time.

12. The mine floor has been graded and reconfigured to prevent stormwater from ponding in the mine area for more than 72 hours.

15. We estimate there is 50,000 cu-yds of topsoil/overburden stockpiled on the mine at this time. The maximum amount of disturbance allowed at the mine is 9.99 acres.

19. The Bond is currently set at \$36,260.00 and is enough to reclaim the disturbed area. It was last evaluated during an inspection on 8-31-2023.