

November 22, 2024

Colorado Division of Reclamation, Mining and Safety Room 215 1001 East 62nd Avenue Denver, CO 80216

Attention: Amy Yeldell

RE: Collett Property, Permit No. M-2024-012 and M-2022-051 Unresolved Problems Report

Ms. Yeldell,

On November 4, 2024, W.W. Clyde & Co. (WW Clyde) received a letter from the Division of Reclamation, Mining and Safety (DRMS) related to outstanding corrective actions required for Collett Property, Permit No. M-2024-012 and M-2022-051. The inspection documenting the "problems" and required corrective actions was conducted on August 7, 2024.

As stated in the November 4, 2024, letter, WW Clyde must submit compliance documentation with corrective actions by December 4, 2024. To date WW Clyde has not performed any corrective actions in response to the inspection report.

Per our telephone conversation on November 11, 2024, WW Clyde will address the Signs and Markers finding no later than December 31, 2024. Depending on subcontractor availability and site accessibility WW Clyde will the install armoring (i.e., riprap) around the culvert inlet/outlet as identified in the inspection report as soon as possible. Due to pending weather conditions, it will most likely not be possible to address the rilling, seeding, and undesirable vegetation conditions until Spring of 2025. WW Clyde will address these issues when snow conditions no longer exist and access to the site will not create additional problems due to wet/muddy conditions.

If you need any more information regarding this project please contact me at 303-906-6611 or by email at cabeyta@wwclyde.net.

Sincerely,

hit & Abyto

Chris Abeyta Environmental Manager

