



STATE OF
COLORADO

Girardi - DNR, Chris <chris.girardi@state.co.us>

Bachus Pit, M1995034- Inspection Problem Past Due

1 message

Girardi - DNR, Chris <chris.girardi@state.co.us>

Tue, Dec 31, 2024 at 9:32 AM

To: abshawnee12@yahoo.com

Cc: Jared Ebert - DNR <jared.ebert@state.co.us>

Good morning,

Attached to this email is a Notice of Outstanding Corrective Action Letter for an inspection problem noted in the September 2024 Inspection Report sent on November 8, 2024.

Please note you will have 30 days from the date of this letter to address the Outstanding Corrective Action.

A hard copy will not be mailed unless requested.

Please feel free to contact me if you have any questions.

Have a great day and happy New Year,
Chris

Chris Girardi

Environmental Protection Specialist Intern



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P: (720) 793-3041

Physical: 1313 Sherman Street, Room 215, Denver, CO 80203

Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

chris.girardi@state.us.co | <https://drms.colorado.gov/>



NoticePastDue_InspectionProblem_BachusPit_M1995034.pdf

321K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

December 31, 2024

Mr. Adrian Absmeier
Absmeier Landscaping
P.O. Box 1134
Alamosa, CO 81101

Re: Notice of Outstanding Corrective Action, Bachus Pit, Permit No. M-1995-034

Mr. Absmeier:

On September 6, 2024, the Division of Reclamation, Mining and Safety (Division/DRMS) performed a routine monitoring inspection of the Bachus Pit, 1995-034. As a result of the inspection, the Division cited a problem, see below, that had a corrective action due date of December 6, 2024. To date documentation that the problem has been resolved remains outstanding. Please resolve the corrective action and provide evidence of the resolution on or before January 30, 2025.

Please note that if the corrective action is not properly addressed, and evidence provided to the Division by the date provided above, the listed problem could be escalated to the level of possible violation and referred to the Mined Land Reclamation Board for further action.

1. INSPECTION TOPIC: Revegetation

PROBLEM: There are state-listed noxious weeds present on site. This is a problem for failure to employ weed control methods for state listed noxious weed species within the permitted area, and to reduce the spread of weeds to nearby areas as required by Section 3.1.10 (6) of the rule.

CORRECTIVE ACTIONS: The Operator shall develop a Weed Control Plan and submit this plan as well as a timeline for its implementation as a Technical Revision to the permit. The Technical Revision will be submitted to the Division by the corrective action due date noted above.

If you have any questions, please contact me by email at chris.girardi@state.co.us.

Sincerely,





Chris Girardi
Environmental Protection Specialist Intern

cc: Jared Ebert; DRMS