



January 23, 2025

Nikie Gagnon
Division of Reclamation, Mining & Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: Permit No. M-2004-044 – Tucson South Resource
Technical Revision Request 4 – Hydrologic Balance/Sediment Control

Holcim is submitting a technical revision to the mining plan to include construction, maintenance, and monitoring of the sediment basin at Outfall 004. Following the December 23, 2024 breach of the sediment basin, Holcim immediately reinforced the berms with approximately 500 tons of overburden. The berms are wider, taller, and compacted than the previous berms. Monitoring will occur daily when pumping is occurring.

If you have any questions, please feel free to contact me at 702-379-4623.

Sincerely,

A handwritten signature in black ink, appearing to read 'Wyatt R. Webster', written over a horizontal line.

Wyatt R. Webster
Environmental & Land Manager