

January 27, 2025

Division of Reclamation, Mining, and Safety
Department of Natural Resources
1313 Sherman St., Room 215
Denver, CO 80230

RE: Annual Report

Greetings,

There has been no new mining activity. Stockpiles of processed materials are about depleted opening up a previously mined area where a deposit can be mined before opening up new ground.

The area described of irrigation tail water is draining well as described and mentioned in the Inspection report conducted June 12th.

Weeds were sprayed with very few individual plants along the roadway entrance. Crop grass and other vegetation was stunted due to a late frost. Grazing was used in the undisturbed fields to lower growth as the late frost and cold spring temperatures limited a hay crop.

A map, satellite imagery, and a narrative letter are included.

Thank you,

A handwritten signature in black ink, appearing to read "Rick Noland". The signature is written in a cursive, slightly stylized font.

Rick Noland
President
Noland, Inc.