

**COLORADO** Division of Reclamation, Mining and Safety

### Department of Natural Resources

## **General Information**

### Disclaimer

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

#### Select Permit Number \*

Only Permit Numbers with currently due Annual Reports and Fees will be listed. If nothing appears in the dropdown box below, there are no annual fees or reports due for any of your permits. M1974004

#### Select Anniversary Date \*

02-15-2025

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

# Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee \*

I understand and agree to the terms

## **General Information**

#### **Permittee Name**

Martin Marietta Materials, Inc.

#### **Operation Name**

Specification Aggregates Quarry

Permit Number	Fee Due	Permit Acreage
M1974004	791.00	389.13
County	Anniversary Date	Current Bond Amount
Jefferson	02-15-2025	7240331.00

Proceed

## **Contact Information**

Here is the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information at the bottom of this page. Indicating that it is inaccurate will send an e-mail to notify your administrator to make the appropriate changes.

### **Permittee Contact Information**

Permittee Contact N Phillip Courtney	lame				
Permittee Company         Martin Marietta Materials, Inc.         Permittee Address 1         1627 Cole Blvd, Suite 200					
Permittee City	Permittee State	Permittee Zip			
Lakewood	СО	80401			
Permittee Phone #	Permittee Fa	ax #			
<b>Permittee Phone #</b> 7206126232	Permittee Fa	ax #			
Permittee Contact E	mail Address	ax #			
7206126232 Permittee Contact E phillip.courtney@martir	<b>Email Address</b> nmarietta.com	ax #			
7206126232	mail Address	ax #			
7206126232 Permittee Contact E phillip.courtney@martir Permitting Contact Phillip Courtney Permitting Company	Email Address Inmarietta.com Ontact Info Name	ax #			
7206126232 Permittee Contact E phillip.courtney@martir Permitting C Permitting Contact	Email Address Inmarietta.com Ontact Info Name Y Ils, Inc. 1	ax #			
7206126232 Permittee Contact E phillip.courtney@martir Permitting Contact Phillip Courtney Permitting Company Martin Marietta Materia Permitting Address	Email Address Inmarietta.com Ontact Info Name y Ils, Inc. 1 200	ax #			
7206126232 Permittee Contact E phillip.courtney@martin Permitting Contact Phillip Courtney Permitting Company Martin Marietta Materia Permitting Address 1627 Cole Blvd, Suite 2	Email Address Inmarietta.com Ontact Info Name y Ils, Inc. 1 200	ex #			

#### **Permitting Contact Email Address**

phillip.courtney@martinmarietta.com

Inspection Contact Info							
Inspection Contact Name							
Phillip Courtney							
Inspection Company Martin Marietta Materials, Inc. Inspection Address 1							
					1627 Cole Blvd, Suite 200		
					Inspection Address 2		
Inspection City	Inspection State	Inspection Zip					
Lakewood	СО	80401					
Inspection Phone # Inspection Fax #		ax #					
7206126232							
7206126232 Inspection Contact Em	nail Address						
Inspection Contact Emphillip.courtney@martinma	arietta.com act information listed at	pove correct? If it is not correct your organization's					
Inspection Contact Emphillip.courtney@martinma Is the Permitting Cont Administrator will reco	arietta.com						
Inspection Contact Emphillip.courtney@martinma	arietta.com act information listed at						
Inspection Contact Emphillip.courtney@martinma Is the Permitting Cont Administrator will reco	arietta.com act information listed at						
Inspection Contact Emphillip.courtney@martinma Is the Permitting Cont Administrator will reco	arietta.com act information listed at						
Inspection Contact Emphillip.courtney@martinma Is the Permitting Cont Administrator will reco	arietta.com act information listed at						
Inspection Contact Emphillip.courtney@martinma Is the Permitting Cont Administrator will reco	arietta.com act information listed at						
Inspection Contact Emphillip.courtney@martinma Is the Permitting Cont Administrator will reco	arietta.com act information listed at						

# Annual Report Questions

Annual Report Questions		
Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.		
<ol> <li>Is the site identification sign posted in accordance with Rule 3.1.12(1).</li> <li>Yes No</li> </ol>		
<ul> <li>2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *</li> <li>Yes </li> <li>No</li> </ul>		
<ul> <li>3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? *</li> <li>If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.</li> <li>Yes </li> </ul>		
4. Please enter the date of last activity at the mine (excavation, processing or hauling). Or, if activity has not yet begun, please indicate so.*		
No activity yet <sup>(e)</sup> Yes, activity has begun 2/10/2025		
<ul> <li>5. Does the mine operate more than 180 days per year? *</li> <li>If "NO", please review Rule 1.13 to assure that your mine is in compliance.</li> <li>Yes No</li> </ul>		
6. Has this mine been granted approval of TEMPORARY CESSATION Status? *		
7. Has this mine been granted approval for INTERMITTENT OPERATION? * (?) <ul> <li>Yes <ul> <li>No</li> </ul> </li> </ul>		
For the following questions, please note that numeric values must include one decimal place, such as "0.0" for zero acres, or 10.2 instead of 10.23.		
8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 280.0		
9. Number of acres that were newly affected during the current report year ${f \star}$ $(?)$ 0.0		
<b>10.</b> Number of acres that were reclaimed during the current report year. <b>*</b> (?) 4.1		
<b>11. Estimated new acreage to be affected in the next report year. *</b> (?) 5.0		
<ul> <li><b>12. Estimated acres to be reclaimed in the next report year.</b> * (?)</li> <li>2.0</li> </ul>		
13. Total acres in various stages of reclamation, since permitted mining activities began:		
Total acres backfilled <b>*</b> (?)		

```
Total acres graded * (?)
82.1
Total acres seeded with approved mix * (?)
82.1
Seed Application Method *
Hydro seeding
Total acres fertilized with aproved fertilizer * (?)
0.0
Total acres with topsoil replaced * (?)
82.1
Topsoil replacement depth (in.) * (?)
8.0
Total acres mulched with approved mulch * (?)
82.1
Mulch application rate (tons/ac) * (?)
0.1
Mulch Application Method *
Hydromulching
```

Previous Proceed

# Annual Report Questions

14. Is weed cont	rol being conducted in accordance with an	approved Weed Control Plan? *		
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.				
● <mark>Yes</mark> ○ No ○ N	J/A			
15. Is adequate	topsoil reserved for reclamation, based on	your approved permit? *		
If "NO", please expla				
● <mark>Yes</mark> ○ No ○ N	J/A			
16. Is the reserv	ed topsoil vegetated/stabilized in accorda	nce with Rule 3.1.9(1)? *		
If "NO", please expla	If "NO", please explain			
🔵 Yes 🔵 No 💿 <mark>N</mark>	I/A			
-	s exposed groundwater, is the site in comp te Engineer (Well Permit, S.W.S.P., and/or			
🖲 <mark>Yes</mark> 🔘 No 🔘 N	I/A			
18. Are all hazar	dous materials stored within approved spil	l containment structures? *		
💿 <mark>Yes</mark> 🔘 No 🔘 N	I/A			
19. Is your finan	cial warranty value sufficient to cover the	cost to complete reclamation? *		
● <mark>Yes</mark> ○ No ○ N	I/A			
20. Is your basis	for legal right to enter still valid? $^{f *}$			
● <mark>Yes</mark> ○ No				
21. Does your pe	ermit require you to submit monitoring info	rmation annually? *		
🖲 <mark>Yes</mark> 🔵 No 🔵 N	I/A			
<b>Required Monito</b>	ring Results Upload *			
Only PDF formatted	files can be uploaded.			
24180001_2025 Sp	pec Agg Report_FINAL.pdf	94.08MB		
the Extraction of that accurately d acreages specifie	lepicts the permit boundary, current affected in items 8-12 and 15. *	or 34-32.5-116), attach a map to this report		
*	files can be uploaded.			
Spec Agg DRMS 20	025 Annual Report Map.pdf	687.75KB		
23. If you have s	supplemental information you would like to	provide, please upload it here.		
Only PDF formatted	files can be uploaded.			
artesian flows a	uires submittal of final abandonment repor nd no later than 12 months for all other cor our exploration/prospecting activities, have	npleted drill holes. If drill holes are a		

Previous Proceed

Annual Fe	ee Payment
-----------	------------

## **Annual Fee Payment**

Payment Confirmation Number \* (?)

244195734

## Signature

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. \*

I Agree

If you do not see the "Submit" button after completing your report, try to un-check and then re-check the "I Agree" box.

Previous