



LOCATION MAP

MAP FEATURES

DISTURBED AREA	PROPERTY BOUNDARY
TOPSOIL STOCKPILES	AFFECTED LAND BOUNDARY
RECLAMATION AREAS	STREAM / DITCH
LAKE / POND	DENVER WATER DEPT.
BUILDING	Contour Interval: 50 feet
ROAD	

REVISION	DATE
Revised for 2011 Annual Report	2/22/12
Revised for 2012 Annual Report	2/27/13
Revised for 2013 Annual Report	2/26/14
Revised for 2014 Annual Report	2/24/15
Revised for 2015 Annual Report	3/4/16
Revised for 2016 Annual Report	3/3/2017
Updated dates and imagery	3/4/2019
Revised for 2020 Annual Report	3/4/2021
Revised for 2021 Annual Report	3/1/2022

Clímax Molybdenum
A Freeport-McMoRan Company
HENDERSON OPERATIONS
1746 County Road
Empire, Colorado 80438

HENDERSON MINE
MLRB Permit No. M-77-342
Annual Reclamation Report

Aquionix
EHS Services
5545 W. 56th Ave.
Pueblo, CO 81003
303-289-7520
www.aquionix.com

DESIGNED BY:
DRAWN BY: MT/KV (Aquionix)
DATE DRAWN: 8/7/2017

SCALE: 1/4,800

S:\arcGIS and AutoCAD files\CHC - Henderson GIS\mxd\mine\DRP\AS Reports