

April 24, 2025

Art Etter Bowie Resources, LLC (BRL) P.O. Box 1488 Paonia, CO 81428

## Re: Bowie No. 2 Mine, Permit C-1996-83, Delay of Inspection for Bond Release Number 4 (SL-04)

Dear Mr. Etter:

Per Rule 3.03.2(2), the Division must perform an inspection of the sites of interest in your SL-04 application. Normally, this inspection would be conducted within 30 days of our completeness determination for the application. (The Division found the application complete today, 24 April 2025.) However, we have the option to delay the inspection due to seasonal limitations. Because some of the sites are remote, the Division is going to delay the inspection until June to insure that there is safe access to the sites. After considering the schedules of Division staff, we want to perform the inspection on June 24<sup>th</sup> and/or June 25<sup>th</sup> of this year.

Please let me know if that schedule is problematic for you.

Thank you,

Phot D. Zh

Robert D. Zuber, P.E. Environmental Protection Specialist

Copied via email: Tamme Bishop, Consulting Engineer

