



STATE OF
COLORADO

Girardi - DNR, Chris <chris.girardi@state.co.us>

King Pit M1987012- Approval of Extension to complete Corrective Actions

1 message

Girardi - DNR, Chris <chris.girardi@state.co.us>

Wed, May 21, 2025 at 12:14 PM

To: Paul Bottini <paul@southwayco.com>

Cc: Jared Ebert - DNR <jared.ebert@state.co.us>, PFM Consulting <pfmconsultingcompany@gmail.com>

Hello Mr. Bottini,

Attached to this email is correspondence granting approval of an extension to complete the remaining corrective actions at the King Pit, permit number M-1987-012.

A hard copy will not be delivered unless requested. Please feel free to reach out if you have any questions.

Thanks,

Chris Girardi

Environmental Protection Specialist Intern



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P: (720) 793-3041

Physical: 1313 Sherman Street, Room 215, Denver, CO 80203

Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

chris.girardi@state.us.co | <https://drms.colorado.gov/>



ExtensionApproval_CorrectiveActions_KingPit_M1987012.pdf
329K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

May 21, 2025

Mr. Paul Bottini
Southwest Ready-Mix, Inc.
117 White Pine Dr.
Alamosa, CO 81101

**Re: Approval of Extension Request to Complete Outstanding Corrective Actions
King Pit, Permit No. M-1987-012**

Dear Mr. Bottini:

On September 5, 2024, the Division of Reclamation, Mining and Safety (“Division” or “DRMS”) performed a routine monitoring inspection of the King Pit, M-1987-012. As a result of the inspection, the Division cited problems that require corrective actions. The Division sent a Notice Past Due of Inspection Problems Letter on December 31, 2024 and on January 24, 2025, and February 7, 2025 the Division received responses.

The Operator has requested a 90-day extension to complete the remaining outstanding corrective actions due to equipment issues. The Division hereby provides approval of an extension of 90 days to complete the remaining corrective actions.

Please provide documentation that earthwork activities have removed erosion gullies in the South Pit Area and decreased the North Pit highwall length to no greater than 300 feet by **August 28, 2025**. Please note that if the corrective actions are not properly addressed, and evidence provided to the Division by the date provided above, the listed problems could be escalated to the level of possible violation and referred to the Mined Land Reclamation Board for further action.

If you have any questions, please contact me by telephone at (720) 793-3041, or by email at chris.girardi@state.co.us.

Sincerely,

Chris Girardi
Environmental Protection Specialist Intern



cc: Jared Ebert; DRMS
Jodi Schreiber, PFM Consulting LLC