



STATE OF
COLORADO

Gibson - DNR, Amber <amber.gibson@state.co.us>

Inspection Report, Mesa DeMaya Pit

Brian Heguy <brian.heguy@lasanimascounty.org>
To: "Gibson - DNR, Amber" <amber.gibson@state.co.us>

Wed, May 28, 2025 at 5:29 PM

Good morning Amber.

We replaced missing boundary markers at Mesa DeMaya Pit.

Refer to photos on attachment.

GPS Coordinates: 37.49446*N , 103.62459*W

37.49465*N , 103.62479*W

37.49492*N , 103.62503*W

37.49518*N , 103.62511*W

37.49560*N , 103.62508*W

37.49557*N , 103.62394*W

Had poor cell service at Pit, hope GPS Coordinates are accurate?

Let me know if you need additional information.

Thank you,

Brian

From: Gibson - DNR, Amber <amber.gibson@state.co.us>
Sent: Wednesday, April 9, 2025 12:02 PM
To: Keith Woodring <keith.woodring@lasanimascounty.org>
Cc: Brian Heguy <brian.heguy@lasanimascounty.org>
Subject: Inspection Report, Mesa DeMaya Pit

Good afternoon,

[Quoted text hidden]

IMG_20250528_0001.pdf
5236K

Sent from my iPhone





















