




Schwartzwalder Daily Summary Report



Report Date:	6/25/2025	Lead Operator:	Patrick D
		Assistant Operator(s):	Bryant A
Effluent Discharged:	0.140 Mgal	MW-18 Level:	155.7 ft
Average Flowrate:	102.2 gpm	Transducer Level:	271.6 ft
Effluent to Date:	2.840 Mgal		



Finished Water Quality			
Parameters	Temp	pH	Cond
Values	20°C	7.52	150 µS/cm

Chemical Inventory			
Chemicals	Antiscalant	NaOH	BaCl
Vol. Used	3 Gal	13 Gal	3 Gal
Vol. Remaining	419 Gal	106 Gal	33 Gal
Vol. Staged	0 Gal	333 Gal	240 Gal
Days Available	140 Days	33 Days	91 Days

Safety Issues/Concerns:

- N/A

Notes:

- Item B32 Completed. Installed Auto Sampler.
- Made enclosure and mounted Ethernet Extender.
- Transferred 152 gallons of 50% NaOH. Washed out used Cuastic tote. This causes the pH and Flow to fluctuate as we were using Permate Water for cleaning.
- Plant housekeeping and weedwhacking around the WTP.
- Collected and delivered Outfall 001A Quarterly WET sample and Outfall 001A TSS & COD.
- Prepped plant for use of forklift for Garage repair on 6/26/25.



Schwartzwalder Daily Summary Report 6/25/26

1 message

Bryant Acevedo <bryant.acevedo@linkan.com>

Thu, Jun 26, 2025 at 9:58 AM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

Good morning,

See attached for 6/25/25 Summary Report and Pictures of

- Item B32 completed. Installed Auto Sampler.

- Made Enclosure and Mounted Ethernet Extender.

Best,

Bryant Acevedo
Operator Technician



cell: 720-238-6169

linkan.com • bryant.acevedo@linkan.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

3 attachments




IMG_7828.jpeg
854K



IMG_7827.jpeg
2157K



SWTP Daily Summary Report 6.25.25.pdf
239K



TRENDnet

Caution Non-Metallic Enclosure does not provide
grounding between conduit connections. When
metallic conduit is used, use grounding type
bushings and jumper wires.

Types 1, 2, 4, 12 & 13

Use Hub type:

Carlson E996D-E996K

Meyers ST1-ST6

Thomas & Betts 370-376



LISTED



