

Reilley - DNR, Robin <robin.reilley@state.co.us>

DRMS review 2025 July DMR

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Thu, Aug 28, 2025 at 12:03 PM

To: Graham Roberts <graham.roberts@trappermine.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Graham,

Please find the Divisions review of the above mentioned DMR for the Trapper Mine. Thank you for your timely submission of this information. The Division has no concerns.

Best Regards, Robin


Robin Reilley, M.S. GISP Environmental Protection Specialist II



P 303.866.3567| F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203 Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | http://mining.state.co.us





Graham Roberts Trapper Mining Inc. P.O. Box 187 Craig, CO 81626

28 August 2025

Re: Trapper Mine (Permit No. C1981010) Review of DMR's 2025 July

Dear Mr. Roberts:

The Division has received and reviewed the 2025 July Discharge Monitoring Reports (DMRs), including the acute monthly WET testing results for the Trapper Mine. The DMRs were received electronically by the Division on 28 August 2025. Thank you for your timely submittal of this information. Trapper submits DMRs to the Division, in accordance with Rule 4.05.13(2)(a)(iii).

Trapper reported that the following outfalls discharged during the month or during the quarter:

- o No Name Pond #5 NPDES 002
- o Middle Flume NPDES 020

Trapper reported that none of the outfalls requiring acute or chronic WET testing discharged. DMRs for discharging outfalls indicated no exceedences of paramaters. The Division does not have any questions, concerns, or further comments at this time. If you have any questions or need additional information, please contact me.

Sincerely,

Robin Reilley, M.S. GISP

Environmental Protection Specialist II

Robin.reilley@state.co.us

