

United States Department of the Interior

BURLAU OF LAND MANAGEMENT free Roos Field Office 29211 (frehway 184 Dolores Colorad) 81323



In Berly Refer In

\$809

(COV 1 V 122) T 1230 T 1230 T 1249 T 1813

August 29, 2012

Robert Oswałd Colorado Division of Mining Reclamation and Safety 691 County Road 233, Ste A-2 Durango, CO 81301

Dear Mr. Oswald,

On August 09, 2012. James Blair, the Geologist for the Dolores Public Lands Office, inspected the following Eynx-Royal Notice Eevel uranium drilling projects with Ryan Weidert of Eynx Royal. These drilling projects are all focated on BEM lands in the vicinity of Egnar, Colorado, They are known by the following BEM and DRMS serial numbers.

Name	BUM Serial Number		DRMS Serial Number	E		
I retiense hast	CCRC-74221		P-2019-032			
ं संत ^{्रा}	(() -1234	· · ·	p.2009.63-			
1402	CTH -74543		1-2010-012			
Shelerer	COR	•	P. Seeula 1			
LOPRI	CERC # 1647	24 t e 250 :	P=20305022		20	
P1	8 CK - 12 Su	2000 -	p provinció	-	0i •	
(5 B)5 (1935)	C (8 -7 17 b)	•	P_20680.1336			

Copies of each inspection report are included with this letter as attachments. All of these projects were drilled during the 2010 or 2011 drilling season. Only those drill sites that were actually disturbed, and identified as needing additional reclamation or time to re-vegetate, as indicated from 2011 inspection reports were revisited in 2012. Farthwork at all of the sites is complete and all sites are stable. No significant crosion problems were observed that appeared likely to be connected to these drilling projects. Vegetation was established at all sites. A few individual drill holes could have had better vegetation growth, however it was clear that they were on the right path, and returning for additional inspections year after year to monitor a fraction of an acre of vegetation growth would not be an efficient use of funds. The cost to the government to continue visiting these sites likely exceeds any remaining reclamation liability. For this reason, I recommend that CDRMS return the bonds for these projects to 1 ynx-Royal, if CDRMS concurs with this assessment. If you have any additional questions, please contact James Blair at 970-882-6862

Sincerely.

ondue Clementson Field Manager Tres Rios Field Office 1 1 -

Attachments - 7 inspection reports (C): Mike Leidich, Evnx Royal.