

STATE OF COLORADO

DIVISION OF RECLAMATION, MINING AND SAFETY

Department of Natural Resources

1313 Sherman St., Room 215

Denver, Colorado 80203

Phone: (303) 866-3567

FAX: (303) 832-8106



September 28, 2012

Emery Lynn Olin
Bridal Veil Construction
P.O. Box 1821
1796 N. Main Street
Ouray, CO 81427

John W. Hickenlooper
Governor

Mike King
Executive Director

Loretta E. Piñeda
Director

RE: Decision to Deny TR-02, Bridalveil Pit, Permit No. M-2001-054.

Dear Mr. Olin:

By letter dated September 12, 2012, the Division identified adequacy issues for TR-02. The Division did not receive response from the Operator to the Division's adequacy issues and the Operator did not request an extension to the review period. Therefore, on the decision day, September 28, 2012, there were outstanding adequacy issues for TR-02. Subsequently, on September 28, 2012, the Division denied TR-02.

Please contact me at the Division's office in Durango at 691 County Road 233, Suite A-2, Durango, CO 81301, phone (970) 247-5469, if you have any questions.

Sincerely,

Wallace H. Erickson
Environmental Protection Specialist

ec: Russ Means, DRMS GJFO