




**COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY**  
**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Multi Mineral RDD Lease	<b>MINE/PROSPECTING ID#:</b> P-2010-026	<b>MINERAL:</b> Oil Shale/Nahc.	<b>COUNTY:</b> Rio Blanco
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Travis H. Marshall	<b>INSP. DATE:</b> November 5, 2013	<b>INSP. TIME:</b> 11:00
<b>OPERATOR:</b> Shell Frontier Oil & Gas Inc.	<b>OPERATOR REPRESENTATIVE:</b> Flo Vuelas	<b>TYPE OF OPERATION:</b> MP - Mineral Prospecting	
<b>REASON FOR INSPECTION:</b> Normal I&e Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$2,642,533.03	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> U.S.BLM	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> November 7, 2013	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>Y</u>	(SB) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was conducted as part of the normal inspection program conducted by the Division of Reclamation, Mining and Safety (DRMS). Paul Daggett with the BLM White River Field Office and Flo Vuelvas of Shell Frontier Oil and Gas Inc. were present during the inspection

The site was inactive during the inspection. The operator indicated that reclamation of the site would likely begin within the next year.

The overall appearance of all sites observed was organized and free of unnecessary debris.

No evidence of erosion or off site damage from erosion was noted.

No significant infestations of noxious or other problematic weeds were observed at any of the areas visited during the inspection.

No problems or violations were observed during the inspection.

Photos that show the conditions observed during the inspection are included at the end of this report.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3<sup>rd</sup> Street, Room 301, Grand Junction, Colorado 81501, phone no. 970-241-2042.

**PHOTOGRAPHS**



**Inspection Contact Address**

Mr. Florentino Vuelvas  
Shell Frontier Oil & Gas Inc.  
3333 Highway 6 South, M1074A  
Houston, TX 77082-3101

CC: Paul Daggett  
BLM- White River Field Office  
220 East Market Street  
Meeker, CO 81641