STATE OF COLORADO

DIVISION OF RECLAMATION, MINING AND SAFETY Department of Natural Resources

1313 Sherman St., Room 215 Denver, Colorado 80203 Phone: (303) 866-3567 FAX: (303) 832-8106

January 24, 2014

Mr. Timm Comer Manager Environmental Resources Cripple Creek & Victor Mining Co. P. O. Box 191 Victor, Colorado 80860



John W. Hickenlooper Governor

Mike King Executive Director

Loretta Piñeda Director

Re: Cripple Creek & Victor Mining, Co., Cresson Project, M-1980-244 Acceptance of Final Report, Cresson Project, Quality Assurance Monitoring and Test Results, Phase 5 Slide Repair, Teller County, Colorado

Dear Mr. Comer,

The Division of Reclamation, Mining and Safety (Division) has completed the review of the Quality Assurance Monitoring and Test Results for the Phase 5 Slide Repair report dated January 14, 2014.

The construction of the Phase 5 Slide Repair was determined to be in compliance with the approved specifications. The Certification is accepted by the Division.

If you have any questions, please do not hesitate to call me at (303) 866-3567 ext. 8169.

Sincerely U. Cam

Timothy A. Cazier, P.E. Environmental Protection Specialist

Cc: Tom Kaldenbach, DRMS Tim Cazier, DRMS