




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Amick Pit	MINE/PROSPECTING ID#: M-1979-103	MINERAL: Sand and gravel	COUNTY: Rio Blanco
INSPECTION TYPE: Monitoring	INSPECTOR(S): Travis H. Marshall	INSP. DATE: January 30, 2014	INSP. TIME: 11:00
OPERATOR: Meeker Sand & Gravel, Inc.	OPERATOR REPRESENTATIVE: Katie Conrado	TYPE OF OPERATION: 112c - Construction Regular Operation	

REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$70,091.00
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None
WEATHER: Snowing	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: February 10, 2014

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(SB) COMPLETE INSP---- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	(ST) STIPULATIONS----- <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation, Mining and Safety (Division). The Amick Pit is located approximately 4.25 miles east of Meeker, Colorado off of County Road 4. The site is a 112c construction materials operation that includes 94.10 acres with a maximum allowed disturbance of 34 acres. Katie Conrado of Meeker Sand & Gravel was present during the inspection.

The required mine identification sign and boundary markers were in place and in compliance with Rule 3.1.12. The permit boundary markers were comprised of fences and fence posts around the entire perimeter of the mine.

The site was not accessible due to a great amount of snow present on the access road. No active mining was occurring during the inspection due to the inclement weather. The site was free of any unnecessary debris and appeared to be well kept.

A required routine reclamation cost update will be conducted and sent under separate cover.

If you need more information regarding this inspection report please contact Travis Marshall in the DRMS Grand Junction Field Office at (970) 241-2042.

PHOTOGRAPHS



Inspection Contact Address

Katie Conrado
Meeker Sand & Gravel, Inc.
3251 RBC #4
Meeker, CO 81641