

Energy Fuels Resources (USA) Inc. 225 Union Blvd. Suite 600 Lakewood, CO, US, 80228 303 974 2140 www.energyfuels.com

February 14, 2014

M-1997-032

Kathy Rosow Colorado Department of Public Health and Environment Water Quality Control Division 4300 Cherry Creek Drive South Denver, Colorado 80246-1530 Water Quality Control Discharge Permits – Mail Code 2034

STORMWATER PERMIT 2013 REPORT

Re: Energy Fuels Resources (USA) Inc.'s Van 4 Shaft Monogram Mesa Stormwater Annual Report – Metal Mining COR-040248

Ms. Rosow:

Enclosed is the 2013 annual report for Energy Fuels Resources (USA) Inc.'s ("EFRI") Van 4 Shaft Monogram Mesa (the "Mine") Stormwater Discharge Permit COR-040248.

The Mine is located in an arid climate where very little runoff of sufficient quantity can be collected and the occurrence of a discharge is extremely rare. EFRI maintains sampling equipment and has Mine Compliance Technicians prepared to take a sample in the event of a heavy enough rainfall to collect a sample; however, no stormwater sampling was conducted in 2013.

If you have any questions or comments, please do not hesitate to contact me at 303-389-4167.

Yours very truly,

ENERGY FUELS RESOURCES (USA) INC. Jaime Massey Regulatory Compliance Specialist

cc: Harold Roberts Kathy Weinel Frank Filas Bob Oswald (DRMS) Robert Ernst (BLM)

\square	E	C	E	0	V		M
[n]		FE	BI	4	2014		U
	Q	IVISIO	V OF R	ECL	OFFICE AMATIO	N,	

STORMWATER ANNUAL REPORT - METAL MINING (& COAL) COLORADO DEPT. OF PUBLIC HEALTH & ENVIRONMENT Water Quality Control Division

WQCD-P-B2 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Make enough copies of form for each reporting year. Or go to http://www.cdphe.state.co.us/wq/PermitsUnit/stormwater/industrial.html

Check	if	this	is	a

Permittee (Company Name): Energy Fuels Resources (USA) Inc.	ss, etc.
Facility Name: Van 4 Shaft Monogram Mesa	-H
Mailing Address: 225 Union Blvd., Suite 600, Lakewood, CO 80228	
Facility Phone Number: 303-974-2140	
Permit Certification No. COR-04 0248	
Reporting Period: Jan. 1-Dec. 31, 20 $\frac{13}{12}$ (Form is due by Feb. 15 of the following year)	

Each section <u>must</u> be completed. Please print or type.

A. A report on the facility's overall compliance with the SWMP. (Include here a summary of any measures taken to comply with your Stormwater Management Plan (SWMP), to fully implement it, changes or improvements made in any of your Best Management Practices (BMPs), employee training, spills, other problems encountered, etc. How is your plan working?)

The Van 4 Mine was in temporary cessation status during 2013; however, a SWMP

No

is in place for the facility. Three comprehensive inspections of the site were completed in 2013.

The inspections indicated that all BMPs at the site are functioning properly,

and no maintenance was required during the reporting year.

Were changes made to your SWMP?

Yes - Describe changes on a separate sheet.

B. A summary of each comprehensive stormwater facility inspection made, including <u>date, findings, and action</u> <u>taken</u>. (The permit requires at least two comprehensive facility inspections per year - see page 12 of the permit. Include here a summary of those inspections, plus any other comprehensive inspections made. It is not necessary to summarize day-to-day inspections, unless significant problems were noted.)

First Inspection - Date $\frac{3}{\frac{14}{13}}$. Findings, and action taken:

All diversion ditches and stormwater catchments were visually observed and photographed.

All BMPs were observed to be in good working order and no maintenance was required.

Note - form may be reproduced

STORMWATER ANNUAL REPORT - METAL MINING (& COAL) Permit Cert. No. COR-04 0248

Second Inspection - Date 6 / 3 /13. Findings, and action taken:

All diversion ditches and stormwater catchments were visually observed. All BMPs

were observed to be in good working order and were not observed to need maintenance.

Other Inspections - Date $\frac{11}{11}$. Findings, and action taken:

All diversion ditches and stormwater catchments were visually observed. All BMPs

were observed to be in good working order and were not observed to need maintenance.

C. Results and interpretation of any stormwater monitoring performed. Attach a separate sheet with the lab results. (Monitoring is not a requirement under the permit, unless you were specifically directed to do so by the Division. However, the results of any stormwater monitoring that you performed on your own should be reported here.)

Yes

✓ No Monitoring Results Attached?

D. Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

2 - 13 - 2014 Date Signed

Signature of Permittee (legally responsible person)

Frank Filas

Name (printed)

VP, Permitting and Environmental Affairs

Title

Use additional pages as needed.

ar6/06mm