

Annual Fee & Map (no Report)

RECEIVED

APR 03 2014

DIVISION OF RECLAMATION  
MINING AND SAFETY



Found Aluminum  
1/2" Cop PLS 23875  
N1/16

Found Rebar  
No Cop as  
shown upon the  
recorded Plat of  
Alpine Vale Filing 2

Found Aluminum  
2 1/2" Cop PLS 23875  
N1/16

N 01°20'01" E  
1215.30'

S 87°27'26" W

1324.55'

S 67°06'05" W

1269.45'

1291.36'

21.91'

Found Aluminum  
Cop PLS 23875  
N1/16

N 01°41'08" E

Disturbed  
area

Quarry Property  
64.00 ACRES

1323.93'

1357.88'

N 88°56'25" E

1330.81'

N 86°21'13" E

1284.82'

1340.15'

Found GLO  
Brace Cap  
1915

Found Aluminum  
3 1/2" Cop PLS 23875  
E1/16

No changes from 2013.  
Van Egnond Stone Pit Mine

m-1991-080

05-04736

Division of Reclamation, Mining, and Safety

Fee Receipt for M1991080

Russ Van Egmond

000000000

Receipt #: 17222

Date: 04/16/2014

Permit: M1991080

| Payment Method | Revenue Code | Fee Description/Notes             | Amount   |
|----------------|--------------|-----------------------------------|----------|
| 12303 msr      | 4300-01      | Minerals Annual Fees<br>M1991-080 | \$323.00 |
| Receipt Total: |              |                                   | \$323.00 |