

Dmc



RECEIVED

APR 24 2014

DIVISION OF RECLAMATION
MINING AND SAFETY

April 21, 2014

Colorado Division of Reclamation, Mining & Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: Bennett's Gravel Pit, Permit # M-1979-166, Response to Inspection

Staff,

As requested in Mr. Czapl's inspection of March 19, 2014 for the Bennett's Gravel Pit (M-1979-166), I am providing photo documentation that a proper sign has been posted at the above referenced pit. The posting of this sign will correct the problem noted in Mr. Czapl's inspection report.

Please don't hesitate to contact me if you have any additional questions.

Sincerely,

Gayle Lyman
Compliance Manager

Xc: Dustin Czapl, DRMS Grand Junction Field Office

