




P-2009-018

PHOTOS RECEIVED FROM OPERATOR (ON 11/3/2011)
DEMONSTRATING CLOSURE OF DRILL HOLE.

ABOVE : GRADED SITE AFTER DRILL HOLE CLOSURE,
WITH RED FLAG MARKING LOCATION.

NEXT PAGE! STEEL CASING EXTENDING 20" ABOVE
SOIL SURFACE (CENTER OF PHOTO).

- AND -

CUTTING OFF STEEL CASING BELOW SOIL
SURFACE, PRIOR TO WELDING ON STEEL CAP,

RECLAMATION IS COMPLETED. — Bob Jannard DRMS

