

DIVISION OF RECLAMATION,
MINING & SAFETY MINERALS
FEE REPORT MAP FEE

112c Annual Report

Permittee Name:	Lafarge West, Inc. c/o Lafarge North America Inc.	Permit Number:	M-1991-035
Operation Name:	Bluestone Pit	County:	Jefferson
Annual Fee Due:	\$791.00	Anniversary Date:	November 5, 2014
Permit Acreage:	707.00	Current Bond Amt:	\$423,800.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1).

YES NO
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2).

YES NO
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.

YES NO
4. What was the date of last excavation, processing or hauling activity at the mine?

2010
5. Does the mine operate more than 180 days per year?
If "NO", please review Rule 1.13 to assure that your mine is in compliance.

YES NO
6. Has this mine been granted: a) approval of TEMPORARY CESSATION Status?
 b) approval for INTERMITTENT OPERATION?

YES NO
YES NO
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation).

655
8. Number of acres that were newly affected during the current report year.

0
9. Number of acres that were reclaimed during the current report year.

109ac
10. Estimated new acreage to be affected in the next report year.

0
11. Estimated acres to be reclaimed in the next report year.

109ac
12. Total acres in various stages of reclamation, since permitted mining activities began:

Total acres backfilled:	~80	Total acres seeded w/ approved mix:	109	Total acres w/topsoil replaced:	~80	Total acres mulched w/ approved mulch:	
Total acres graded:	~80	Total acres fertilized w/ apvd fertilizer:		Topsoil replacement depth (in.):	3-6	Mulch application rate (tons/ac):	
Seed application method:		Fertilizer application method:		Mulch application method:			

13. Is weed control being conducted in accordance with an approved Weed Control Plan?
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.

YES

NO

N/A
14. Is adequate topsoil reserved for reclamation, based on your approved permit?
If "NO", please explain:

YES

NO

N/A
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)?
If "NO" please explain:

YES

NO

N/A
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)?

YES

NO

N/A
17. Are all hazardous materials stored within approved spill containment structures?

YES

NO

N/A
18. Is your financial warranty value sufficient to cover the cost to complete reclamation?

YES

NO

N/A
19. Is your basis for legal right to enter still valid?

YES

NO
20. Does your permit require you to submit monitoring information annually?
If "Yes", please attach the required monitoring results to this Annual Report.

YES


NO

N/A
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14.
UPDATED MAP ATTACHED: ☒

Division records indicate the following permittee contact information. If this information is not current, please type or print **current** contact information:

Permittee Contact:	Anthony "Marshall" Miller	
Permittee Company:	Lafarge West, Inc. c/o Lafarge North America Inc.	
Address:	8700 W. Bryn Mawr Ave., Ste. 300 Chicago, IL 60631	
Phone Number:	(773) 372-1000	
Fax Number:		
Email Address:	CF.PR.email	


I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.



Signature of Permittee, Corporate Officer, Owner, or Documented Designee

10/31/14

Date



RECEIVED

NOV 06 2014

DIVISION OF RECLAMATION
MINING AND SAFETY

M-1791-035

DRAFT

Project No.:	133-23511-10002
Designed By:	GL
Drawn By:	RP
Checked By:	RJT

MARK	DATE	DESCRIPTION	BY

[illegible]








LAFARGE
BLUESTONE

Project No.:	133-23511-10002
Designed By:	GL
Drawn By	RP
Checked By:	RJT

C-103

Sheet
Bar Measures 1 inch

DRAFT




RECEIVED

NOV 06 2014

**DIVISION OF RECLAMATION
MINING AND SAFETY**

M-1991-035




NRV 06 2014

ALLIANCE FOR MINING AND SAFETY
DIVISION OF REGULATION


M-1991-035




13 TYPICAL SECTION 13
C-102




14 TYPICAL SECTION 14
C-102




15 TYPICAL SECTION 15




9 TYPICAL SECTION 9
C-102



10 TYPICAL SECTION 10
C-102



11 TYPICAL SECTION 11
C-102



12 TYPICAL SECTION 12

LAFARGE
BLUESTONE

Printed No.: 133-23511-10002

Designed By: GL

Drawn By: _____

Checked By: RJT

DRAFT

Sheet
Bar Measures 1 inch

Division of Reclamation, Mining, and Safety

Fee Receipt for M1991035

Lafarge West, Inc. c/o Lafarge North America |

000000000

Receipt #: 18516
Date: 11/06/2014
Permit: M1991035

Payment Method	Revenue Code	Fee Description/Notes	Amount
73345691 msr	4300-MAF0	Minerals Annual Fees M1991-035	\$791.00
Receipt Total:			\$791.00