


# Report



QATESTOCR



**Cripple Creek & Victor Gold Mining Company**

A Joint Venture · ANGLOGOLD ASHANTI (COLORADO) CORP., Manager

**Operations Office**

P.O. Box 191 · 100 North 3<sup>rd</sup> Street  
Victor, Colorado 80860  
(719) 689-2977 – Fax (719) 689-3254



SENT US POSTAL SERVICE EXPRESS MAIL  
7014-0150-0000-6082-6110

November 6, 2014

Mr. Tim Cazier  
Environmental Protection Specialist  
Office of Mine Land Reclamation  
Division of Reclamation, Mining & Safety  
1313 Sherman Street, RM 215  
Denver, CO. 80203

**RECEIVED**

NOV 07 2014

DIVISION OF RECLAMATION  
MINING AND SAFETY

Re: Cresson Project Permit M-1980-244, "Cripple Creek & Victor Gold Mining Company  
Mill Site Earth Works Project Final Report Quality Assurance Monitoring & Test  
Results, Revised Record Drawing 4 of 4."

Dear Mr. Cazier:

Per your e-mail request of October 30, 2014, enclosed please find (3) revised copies of Record Drawing 4 of 4, Mill Site Earthworks Primary Geomembrane. This drawing is located in Appendix A of the above referenced certification report. The drawings were revised to include a signed and dated P.E. stamp.

Please contact me at 719-689-4048 should you have questions.

Sincerely,

Chris Hanks  
Chief Environmental Coordinator

Enclosure: Three copies: "Cripple Creek & Victor gold Mining Company Mill Site Earth Works Project Quality Assurance Monitoring & Test Results, Revised Record Drawing 4 of 4"