



**COLORADO**

**Division of Reclamation,  
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

November 7, 2014

Mr. Timm Comer  
Cripple Creek & Victor Gold Mining Company  
100 N. 3rd Street  
P. O. Box 191  
Victor, CO 80860

**Re: Cripple Creek & Victor Mining, Co., Cresson Project, M-1980-244;  
Acceptance of As-Built Certification Report for Mill Site Earthworks Project**

Dear Mr. Comer:

The Division of Reclamation, Mining and Safety (Division) has completed the review of the Quality Assurance Monitoring and Test Results for the Mill Site Earthworks Project dated January 31, 2014.

The construction of the Mill Site Earthworks Project was determined to be in compliance with the approved specifications. The Certification is accepted by the Division. The construction of above grade appurtenances for this area may proceed.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E.  
Environmental Protection Specialist

ec: Tom Kaldenbach, DRMS

