

RECEIVED

NOV 25 2014

DIVISION OF RECLAMATION,
MINING & SAFETY-MINERALS

112d-3 Annual Report

Permittee Name:	Cotter Corporation	Permit Number:	M-1979-094-HR
Operation Name:	JD-7 Pit	County:	Montrose
Annual Fee Due:	\$1,150.00	Anniversary Date:	December 14, 2014
Permit Acreage:	504.00	Current Bond Amt:	\$39,000.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1). YES NO
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). YES NO
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)?
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. YES NO
4. What was the date of last excavation, processing or hauling activity at the mine? 1982
5. Does the mine operate more than 180 days per year
If "NO", please review Rule 1.13 to assure that your mine is in compliance. YES NO
6. Has this mine been granted: a) approval of TEMPORARY CESSATION Status? YES NO
b) approval for INTERMITTENT OPERATION? YES NO
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation). 402
8. Number of acres that were newly affected during the current report year. 0
9. Number of acres that were reclaimed during the current report year. 0
10. Estimated new acreage to be affected in the next report year. 0
11. Estimated acres to be reclaimed in the next report year. 0

12. Total acres in various stages of reclamation, since permitted mining activities began:


Total acres backfilled:	0	Total acres seeded w/ approved mix:	80	Total acres w/topsoil replaced:	0	Total acres mulched w/ approved mulch:	0
Total acres graded:	20	Total acres fertilized w/ apvd fertilizer:	0	Topsoil replacement depth (in.):	N/A	Mulch application rate (tons):	N/A
Seed application method:	N/A	Fertilizer application method:	N/A	Mulch application method:	N/A		

13. Is weed control being conducted in accordance with an approved Weed Control Plan? YES NO N/A
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.
14. Is adequate topsoil reserved for reclamation, based on your approved permit? YES NO N/A
If "NO", please explain:
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? YES NO N/A
If "NO" please explain:
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? YES NO N/A
17. Are all hazardous materials stored within approved spill containment structures? YES NO N/A
18. Is your financial warranty value sufficient to cover the cost to complete reclamation? YES NO N/A
19. Is your basis for legal right to enter still valid? YES NO
20. Does your permit require you to submit monitoring information annually? YES NO N/A
If "Yes", please attach the required monitoring results to this Annual Report.
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14.
UPDATED MAP ATTACHED: _____

Division records indicate the following permittee contact information. If this information is not current, please type or print current contact information:

Permittee Contact:	Ken Williams	Ken Mushinski
Permittee Company:	Cotter Corporation	
Address:	P.O. Box 700 Nucla, CO 81424	
Phone Number:	(970) 864-7347	858-455-3275
Fax Number:	(970) 864-7287	
Email Address:	CFPR-email	Ken.mushinski@cotterusa.com

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.


Signature of Permittee, Corporate Officer, Owner, or Documented Designee

11/04/14
Date



November 4, 2014

Division of Reclamation, Mining and Safety
Attn: Michelle Ramirez
1313 Sherman Street, Room 215
Denver, CO 80203

RECEIVED

NOV 25 2014

DIVISION OF RECLAMATION
MINING AND SAFETY

Subject: JD-7 Pit Mine Annual Report
File No. M-1979-094 HR

Dear Ms. Ramirez

The JD-7 Pit Mine is located in Montrose County and operates under a 112 permit, with a permitted acreage of 490 acres. This mine has a phased reclamation plan. There was no additional affected acreage during this report year, and no additional disturbance is anticipated for the next report year.


Since there were no changes a new map has not been included with this report. This mine is currently in temporary cessation, per the Division's approval.

The sufficiency of the financial warranty for the above captioned permit has been reviewed by DRMS and Cotter Corporation and was found sufficient to cover the reclamation costs associated with this property.

Enclosed please find a completed annual report form, and a check in the amount of \$1150.00 as payment for the annual fee.

If you need additional information, please call me at 858-455-3275.

Sincerely,
COTTER CORPORATION


Ken Mushinski,
President

DRMSJD7PIT_14

Division of Reclamation, Mining, and Safety

Fee Receipt for M1979094HR

Cotter Corporation

000000000

Receipt #: 18589

Date: 11/25/2014

Permit: M1979094HR

Payment Method	Revenue Code	Fee Description/Notes	Amount
238958 msr	4300-MAF0	Minerals Annual Fees M1979--094HR	\$1,150.00

Receipt Total:	\$1,150.00
----------------	------------