

Appendix B

Photographic Documentation

Appendix B.1 – Photograph Log

Appendix B.2 – Construction Photographs

Appendix B.1

Photograph Log

PHOTOGRAPH LOG

Photo 1 January 17, 2013 Beginning of PSSA Construction	1
Photo 2 January 30, 2013 PSSA Construction Overview	1
Photo 3 March 07, 2013 PSSA Construction Overview	2
Photo 4 March 12, 2013 Underground Working Reclamation	2
Photo 5 March 13, 2013 PSSA Drilling for Blast.....	3
Photo 6 March 15, 2013 Primary Underdrain under Highway 67 Embankment	3
Photo 7 March 21, 2013 PSSA Construction Overview	4
Photo 8 May 06, 2013 PSSA Construction Overview	4
Photo 9 May 16, 2013 PSSA Underdrain Ponds Construction	5
Photo 10 May 18, 2013 PSSA Underdrain Ponds Overview	5
Photo 11 July 09, 2013 PSSA Highway 67 Embankment Construction	6
Photo 12 July 19, 2013 PSSA Highway 67 Embankment Construction	6
Photo 13 July 29, 2013 PSSA Construction Overview	7
Photo 14 August 17, 2013 PSSA Construction Overview.....	7
Photo 15 January 13, 2014 PSSA Excavation.....	8
Photo 16 January 17, 2014 PSSA Excavation.....	8
Photo 17 February 18, 2014 PSSA Closure Drain Drilling.....	9
Photo 18 February 18, 2014 PSSA Embankment Fill.....	9
Photo 19 February 19, 2014 PSSA Embankment Fill.....	10
Photo 20 March 29, 2014 PSSA Embankment Fill	10
Photo 21 April 10, 2014 PSSA Embankment Fill	11
Photo 22 April 12, 2014 PSSA Construction Overview.....	11
Photo 23 April 12, 2014 PSSA Blast Preparation	12
Photo 24 April 16, 2014 Underground Working Reclamation	12
Photo 25 April 23, 2014 PSSA Construction Overview.....	13
Photo 26 May 17, 2014 PSSA Embankment Fill	13
Photo 27 May 19, 2014 PSSA Secondary Underdrain Installation	14
Photo 28 May 19, 2014 PSSA Secondary Underdrain Installation	14
Photo 29 May 22, 2014 PSSA Underground Working Reclamation	15
Photo 30 May 22, 2014 PSSA Primary Underdrain Installation	15
Photo 31 May 22, 2014 PSSA Construction Overview	16
Photo 32 May 28, 2014 PSSA Construction Overview	16
Photo 33 May 28, 2014 PSSA Closure Drain Pipes	17
Photo 34 May 29, 2014 PSSA Subgrade Preparation	17
Photo 35 June 04, 2014 PSSA Closure Drain Subgrade Placement.....	18
Photo 36 June 05, 2014 PSSA Closure Drain Soil Liner Fill Placement.....	18
Photo 37 June 07, 2014 Underdrain Fill at Closure Drain	19
Photo 38 June 10, 2014 PSSA Soil Liner Fill Compaction Testing.....	19
Photo 39 June 10, 2014 PSSA Secondary Geomembrane Installation	20
Photo 40 June 11, 2014 PSSA Secondary Geomembrane Fusion Welding	20

Photo 41 June 13, 2014 PSSA Secondary Geomembrane Vacuum Testing	21
Photo 42 June 16, 2014 PSSA ADR Pad Overview	21
Photo 43 June 16, 2014 PSSA Secondary Geomembrane Fusion Trial Seam.....	22
Photo 44 June 19, 2014 PSSA Secondary Geomembrane Deployment Overview	22
Photo 45 June 26, 2014 PSSA Geomembrane Destructive Testing	23
Photo 46 June 26, 2014 PSSA Secondary Geomembrane Deployment Overview	23
Photo 47 July 02, 2014 PSSA Construction Overview	24
Photo 48 July 03, 2014 Construction of Low Volume Solution Collection Manifold	24
Photo 49 July 03, 2014 PSSA Low Volume Solution Collection Fill Placement.....	25
Photo 50 July 16, 2014 PSSA Construction Overview	25
Photo 51 July 29, 2014 PSSA Geomembrane Installation	26
Photo 52 August 05, 2014 PSSA Construction Overview.....	26
Photo 53 August 07, 2014 PSSA Low Volume Solution Collection Manifold Installation.....	27
Photo 54 August 07, 2014 PSSA Low Volume Solution Collection Manifold Installation.....	27
Photo 55 August 09, 2014 PSSA Construction Overview.....	28
Photo 56 August 10, 2014 PSSA Secondary Geomembrane Deployment	28
Photo 57 August 22, 2014 PSSA Low Volume Solution Collection Fill Placement.....	29
Photo 58 August 23, 2014 PSSA Secondary Geomembrane Deployment	29
Photo 59 August 27, 2014 PSSA Geomembrane Trial Seam Testing.....	30
Photo 60 September 06, 2014 PSSA Construction Overview	30
Photo 61 September 11, 2014 PSSA High Volume Risers Installation	31
Photo 62 September 11, 2014 PSSA High Volume Risers Installation	31
Photo 63 September 11, 2014 PSSA High Volume Risers Installation	32
Photo 64 September 12, 2014 PSSA Geomembrane Vacuum Testing	32
Photo 65 September 13, 2014 PSSA High Volume Risers Installation	33
Photo 66 September 24, 2014 PSSA Drain Cover Fill Placement.....	33
Photo 67 September 25, 2014 PSSA Construction Overview	34
Photo 68 October 03, 2014 PSSA Primary Geomembrane Deployment.....	34
Photo 69 October 04, 2014 PSSA Construction Overview	35
Photo 70 October 06, 2014 PSSA 28-inch Primary Collection Pipe	35
Photo 71 October 07, 2014 PSSA High Volume Solution Collection System Manifold	36
Photo 72 October 08, 2014 PSSA 24-inch Collection Pipe	36
Photo 73 October 10, 2014 PSSA Construction Overview	37
Photo 74 October 21 2014 PSSA High Volume Solution Collections System Riser Pipes.....	37
Photo 75 October 21 2014 PSSA Construction Overview	38

Appendix B.2

Construction Photographs



Photo 1 January 17, 2013 Beginning of PSSA Construction



Photo 2 January 30, 2013 PSSA Construction Overview



Photo 3 March 07, 2013 PSSA Construction Overview



Photo 4 March 12, 2013 Underground Working Reclamation



Photo 5 March 13, 2013 PSSA Drilling for Blast



Photo 6 March 15, 2013 Primary Underdrain under Highway 67 Embankment



Photo 7 March 21, 2013 PSSA Construction Overview



Photo 8 May 06, 2013 PSSA Construction Overview



Photo 9 May 16, 2013 PSSA Underdrain Ponds Construction



Photo 10 May 18, 2013 PSSA Underdrain Ponds Overview



Photo 11 July 09, 2013 PSSA Highway 67 Embankment Construction



Photo 12 July 19, 2013 PSSA Highway 67 Embankment Construction



Photo 13 July 29, 2013 PSSA Construction Overview



Photo 14 August 17, 2013 PSSA Construction Overview



Photo 15 January 13, 2014 PSSA Excavation



Photo 16 January 17, 2014 PSSA Excavation



Photo 17 February 18, 2014 PSSA Closure Drain Drilling



Photo 18 February 18, 2014 PSSA Embankment Fill



Photo 19 February 19, 2014 PSSA Embankment Fill



Photo 20 March 29, 2014 PSSA Embankment Fill



Photo 21 April 10, 2014 PSSA Embankment Fill



Photo 22 April 12, 2014 PSSA Construction Overview



Photo 23 April 12, 2014 PSSA Blast Preparation



Photo 24 April 16, 2014 Underground Working Reclamation



Photo 25 April 23, 2014 PSSA Construction Overview



Photo 26 May 17, 2014 PSSA Embankment Fill



Photo 27 May 19, 2014 PSSA Secondary Underdrain Installation




Photo 28 May 19, 2014 PSSA Secondary Underdrain Installation



Photo 29 May 22, 2014 PSSA Underground Working Reclamation



Photo 30 May 22, 2014 PSSA Primary Underdrain Installation



Photo 31 May 22, 2014 PSSA Construction Overview



Photo 32 May 28, 2014 PSSA Construction Overview



Photo 33 May 28, 2014 PSSA Closure Drain Pipes



Photo 34 May 29, 2014 PSSA Subgrade Preparation



Photo 35 June 04, 2014 PSSA Closure Drain Subgrade Placement



Photo 36 June 05, 2014 PSSA Closure Drain Soil Liner Fill Placement



Photo 37 June 07, 2014 Underdrain Fill at Closure Drain



Photo 38 June 10, 2014 PSSA Soil Liner Fill Compaction Testing



Photo 39 June 10, 2014 PSSA Secondary Geomembrane Installation




Photo 40 June 11, 2014 PSSA Secondary Geomembrane Fusion Welding



Photo 41 June 13, 2014 PSSA Secondary Geomembrane Vacuum Testing



Photo 42 June 16, 2014 PSSA ADR Pad Overview



Photo 43 June 16, 2014 PSSA Secondary Geomembrane Fusion Trial Seam



Photo 44 June 19, 2014 PSSA Secondary Geomembrane Deployment Overview



Photo 45 June 26, 2014 PSSA Geomembrane Destructive Testing



Photo 46 June 26, 2014 PSSA Secondary Geomembrane Deployment Overview



Photo 47 July 02, 2014 PSSA Construction Overview



Photo 48 July 03, 2014 Construction of Low Volume Solution Collection Manifold



Photo 49 July 03, 2014 PSSA Low Volume Solution Collection Fill Placement



Photo 50 July 16, 2014 PSSA Construction Overview



Photo 51 July 29, 2014 PSSA Geomembrane Installation



Photo 52 August 05, 2014 PSSA Construction Overview



Photo 53 August 07, 2014 PSSA Low Volume Solution Collection Manifold Installation



Photo 54 August 07, 2014 PSSA Low Volume Solution Collection Manifold Installation



Photo 55 August 09, 2014 PSSA Construction Overview



Photo 56 August 10, 2014 PSSA Secondary Geomembrane Deployment



Photo 57 August 22, 2014 PSSA Low Volume Solution Collection Fill Placement



Photo 58 August 23, 2014 PSSA Secondary Geomembrane Deployment



Photo 59 August 27, 2014 PSSA Geomembrane Trial Seam Testing



Photo 60 September 06, 2014 PSSA Construction Overview



Photo 61 September 11, 2014 PSSA High Volume Risers Installation



Photo 62 September 11, 2014 PSSA High Volume Risers Installation



Photo 63 September 11, 2014 PSSA High Volume Risers Installation



Photo 64 September 12, 2014 PSSA Geomembrane Vacuum Testing




Photo 65 September 13, 2014 PSSA High Volume Risers Installation



Photo 66 September 24, 2014 PSSA Drain Cover Fill Placement



Photo 67 September 25, 2014 PSSA Construction Overview



Photo 68 October 03, 2014 PSSA Primary Geomembrane Deployment




Photo 69 October 04, 2014 PSSA Construction Overview



Photo 70 October 06, 2014 PSSA 28-inch Primary Collection Pipe



Photo 71 October 07, 2014 PSSA High Volume Solution Collection System Manifold



Photo 72 October 08, 2014 PSSA 24-inch Collection Pipe



Photo 73 October 10, 2014 PSSA Construction Overview



Photo 74 October 21 2014 PSSA High Volume Solution Collections System Riser Pipes



Photo 75 October 21 2014 PSSA Construction Overview