



**Cripple Creek & Victor Gold Mining Company**

A Joint Venture · ANGLOGOLD ASHANTI (COLORADO) CORP., Manager

**Operations Office**

P.O. Box 191 · 100 North 3<sup>rd</sup> Street  
Victor, Colorado 80860  
(719) 689-2977 – Fax (719) 689-3254



SENT US POSTAL SERVICE EXPRESS MAIL  
EF 006310990 US, EF060929209

November 19, 2014

Mr. Tim Cazier  
Environmental Protection Specialist  
Office of Mine Land Reclamation  
Division of Reclamation, Mining & Safety  
1313 Sherman Street, RM 215  
Denver, CO. 80203

Re: Cresson Project Permit M-1980-244, "Cripple Creek & Victor Gold Mining Company  
Squaw Gulch VLF Pregnant Solution Storage Area Project Final Report Quality  
Assurance Monitoring & Test Results."

Dear Mr. Cazier:

Enclosed please find (2) copies of the "Cripple Creek & Victor Gold Mining Company Squaw Gulch VLF Pregnant Solution Storage Area Project Quality Assurance Monitoring & Test Results" as completed by Amec Earth & Environment, dated November 2014.

This report details work associated with the Cresson Project that was performed under specific criteria established in Amendment No. 10 of Permit No.M-1980-244 as approved by the MLRB. This report documents the Construction Quality Assurance and Construction Quality Control services provided by AMEC from January 2013 through November 2014 for the Squaw Gulch VLF Pregnant Solution Storage Area.

CC&V has also placed this report on our ftp site as discussed with you previously.

Please contact me at 719-689-4048 should you have questions.

Sincerely,

Chris Hanks  
Chief Environmental Coordinator