


Report



QATESTOCR

DNC **RECEIVED**

DEC 08 2014

Page 2 of 3

**DIVISION OF RECLAMATION,
MINING & SAFETY MINERALS
FEE REPORT MAP**

112c Annual Report

Permittee Name:	ACA Products, Inc.	Permit Number:	M-1979-010
Operation Name:	Avery Construction Pit	County:	Chaffee
Annual Fee Due:	\$791.00	Anniversary Date:	January 15, 2015
Permit Acreage:	108.00	Current Bond Amt:	\$204,050.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1). YES NO
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). YES NO
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? YES NO
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.
4. What was the date of last excavation, processing or hauling activity at the mine? Current +
5. Does the mine operate more than 180 days per year? YES NO
If "NO", please review Rule 1.13 to assure that your mine is in compliance.
6. Has this mine been granted: YES NO
a) approval of TEMPORARY CESSATION Status? YES NO
b) approval for INTERMITTENT OPERATION?
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation). 108 Acres
8. Number of acres that were newly affected during the current report year. 0
9. Number of acres that were reclaimed during the current report year. N/A
10. Estimated new acreage to be affected in the next report year. 0
11. Estimated acres to be reclaimed in the next report year. 2
12. **Total acres** in various stages of reclamation, since permitted mining activities began:

Total acres backfilled:	<u>1 Acre</u>	Total acres seeded w/ approved mix:	<u>2 Acres</u>	Total acres w/topsoil replaced:	<u>2 Acres</u>	Total acres mulched w/ approved mulch:	<u>N/A</u>
Total acres graded:	<u>2 Acres</u>	Total acres fertilized w/ apvd fertilizer:	<u>N/A</u>	Topsoil replacement depth (in.):	<u>6"</u>	Mulch application rate (tons/ac):	<u>N/A</u>
Seed application method:	<u>Broadcast</u>	Fertilizer application method:	<u>N/A</u>	Mulch application method:	<u>N/A</u>		

13. Is weed control being conducted in accordance with an approved Weed Control Plan? YES NO N/A
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.
14. Is adequate topsoil reserved for reclamation, based on your approved permit? YES NO N/A
If "NO", please explain:
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? YES NO N/A
If "NO" please explain:
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? YES NO N/A
17. Are all hazardous materials stored within approved spill containment structures? YES NO N/A
18. Is your financial warranty value sufficient to cover the cost to complete reclamation? YES NO N/A
19. Is your basis for legal right to enter still valid? YES NO
20. Does your permit require you to submit monitoring information annually? YES NO N/A
If "Yes", please attach the required monitoring results to this Annual Report.
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14.
UPDATED MAP ATTACHED: X

Division records indicate the following permittee contact information. If this information is not current, please type or print **current** contact information:

Permittee Contact:	Michael D. Coleman	
Permittee Company:	ACA Products, Inc.	
Address:	702 Gregg Drive P.O. Box 1887 Buena Vista, CO 81211	
Phone Number:	(719) 395-3790	
Fax Number:	(719) 395-3794	
Email Address:	CF.PR.email	

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.

Michael D. Coleman
Signature of Permittee, Corporate Officer, Owner, or Documented Designee

Dec 9, 2014
Date



P.O. Box 1887, 702 Gregg Drive, Buena Vista, CO 81211
Ph: (719) 395-3790 Fax: (719) 395-3794

RECEIVED

DEC 08 2014

**DIVISION OF RECLAMATION
MINING AND SAFETY**

Division of Reclamation, Mining and Safety
1313 Sherman St., Room 215
Denver, Colorado 80203

December 3, 2014

RE: Avery Pit Annual Report Permit #M-1979-010

The Avery Pit is an active year round operation. The 2014 mining and the anticipated mining for 2015 locations are exhibited on the map. There was not any reclamation for 2014 and the projected reclamation for 2015 is marked on map.

Respectfully,

A handwritten signature in blue ink that reads "Michael D. Coleman".

Michael D. Coleman
President

Division of Reclamation, Mining, and Safety

Fee Receipt for M1979010

ACA Products, Inc.

000000000

Receipt #: 18626

Date: 12/08/2014

Permit: M1979010

Payment Method	Revenue Code	Fee Description/Notes	Amount
67001 msr	4300-MAF0	Minerals Annual Fees M1979-020	\$791.00
Receipt Total:			\$791.00