



QUIKRETE® - Denver  
2660 W. 64<sup>th</sup> Ave  
Denver, CO 80221  
(303) 429-2111

December 18, 2014

Dustin Czapla  
CO Division of Reclamation, Mining, and Safety  
Grand Junction Field Office  
101 South 3<sup>rd</sup> St. Room 301  
Grand Junction, CO 81501

**RECEIVED**  
DEC 22 2014  
GRAND JUNCTION FIELD OFFICE  
DIVISION OF  
RECLAMATION MINING & SAFETY

RE: Response to 9-10-2014 Inspection Report of Lily Mines, ID# M-1987-028

Dustin,

Thank you for your time on the phone yesterday. Per our conversation, due to the narrow window of available operation at the mine site we were unable to get a geotechnical engineer on the site before the end of the season. I will include a placeholder in the annual report due in March and note that a visual geotechnical inspection of the existing highwall(s) will be submitted as an addendum in early summer 2015. I will get the inspection scheduled as soon as we can gain access to the mine site and most of the snow has melted off.

Thank you again for your time and understanding.

Regards,

A handwritten signature in black ink, appearing to read "Eric Leigh".

Eric Leigh  
Regional Operations Manager  
Quikrete – Colorado  
303-429-2111

