




**COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY**  
**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> White River Pit	<b>MINE/PROSPECTING ID#:</b> M-2008-070	<b>MINERAL:</b> Gravel	<b>COUNTY:</b> Rio Blanco
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Travis H. Marshall	<b>INSP. DATE:</b> July 3, 2015	<b>INSP. TIME:</b> 12:00
<b>OPERATOR:</b> OWL SWD Operating, LLC	<b>OPERATOR REPRESENTATIVE:</b> Seth Peters	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	

<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$106,548.00
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> July 8, 2015

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>Y</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(SB) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation, Mining and Safety. The WRC Gravel Pit is located approximately 13 miles west of Meeker, Colorado. The WRC Gravel Pit is a 191.83 acre 112c construction materials mining operation. Seth Peters and Doug Wheeler of OWL SWD Operating, LLC accompanied the inspector during the inspection.

The mine identification sign and the affected area boundary markers were present and in compliance with Rule 3.1.12.

The site was active during the inspection. Various stockpiles of construction material were observed.

The purpose of the inspection was to observe the completed solid waste disposal cell located in Phase 1 and determine whether or not an acreage reduction was in order to remove the cell from the reclamation permit acreage. The approved reclamation for the 6.5 acre cell area is completion of the waste disposal cell and CDPHE certification to begin accepting waste at the facility. The Operator has completed both requirements and the 6.5 acre disposal cell is eligible to be removed from the permit area and must be done so prior to accepting any waste in the disposal cell.

No off-site damage was observed during the inspection.

Photos that show the conditions observed during the inspection are included at the end of this report.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3<sup>rd</sup> Street, Room 301, Grand Junction, Colorado 81501, phone no. 970-241-2042.

### **PHOTOGRAPHS**











**Inspection Contact Address**

Seth Peters  
OWL SWD Operating, LLC  
4775 Larimer Pkwy, Suite 200  
Johnstown, CO 80534