



Environment and Social Responsibility

Newmont Mining Corporation
Cripple Creek & Victor Gold Mining Co.
P.O. Box 191
Victor, CO 80860
T 719-689-2977
F 719-689-3254
brigitte.florquist@newmont.com

USPS Priority Mail # EF006310853 and # EF 006310867

October 13, 2015

Mr. Tim Cazier
Environmental Protection Specialist
Office of Mine Land Reclamation
Division of Reclamation, Mining & Safety
1313 Sherman Street, RM 215
Denver, CO. 80203

RECEIVED

OCT 14 2015

DIVISION OF RECLAMATION
MINING AND SAFETY

Re: Cresson Project Permit M-1980-244,"*Cripple Creek & Victor Gold Mining Company Squaw Gulch VLF Phase I (9450'-9550' Bench) Project Final Report Quality Assurance Monitoring & Test Results.*"

Dear Mr. Cazier:

We are providing via our ShareFile site and with a follow up hard copy the certification report of the "*Cripple Creek & Victor Gold Mining Company Squaw Gulch VLF Phase I (9450'-9550' Bench) Project Quality Assurance Monitoring & Test Results*" as completed by Amec Earth & Environment, dated October 2015.

This report details work associated with the Cresson Project that was performed under specific criteria established in Amendment No. 10 of Permit No.M-1980-244 as approved by the MLRB. This report documents the Construction Quality Assurance and Construction Quality Control services provided by AMEC from November 2014 through September 2015 for the Squaw Gulch VLF Phase I (9450' to 9550' Bench).

Please contact me at 719-689-4048 should you have questions.

Sincerely,

A handwritten signature in black ink that reads "Chris Hanks". The signature is fluid and cursive, with the first name "Chris" and last name "Hanks" clearly distinguishable.

Chris Hanks
Chief Environmental Coordinator