



COLORADO

**Division of Reclamation,
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

December 18, 2015

Mr. Jack Henris
Cripple Creek & Victor Gold Mining Company
100 N. 3rd Street
P. O. Box 191
Victor, CO 80860

**Re: Cripple Creek & Victor Mining, Co., Cresson Project, M-1980-244;
Approval for Quality Assurance Monitoring & Test Results Final Report for Squaw Gulch
VLF Phase 1 (9,450 to 9,550 Bench)**

Dear Mr. Henris:

The Division of Reclamation, Mining and Safety (Division) has received your December 17, 2015 Responses to the Division's final comments based on the Division's December 15, 2015 review comments related to the Quality Assurance Monitoring and Test Results for the Squaw Gulch VLF Phase 1 (9,450 to 9,550 Bench). The responses from Amec Foster Wheeler are considered adequate.

The construction of the Squaw Gulch VLF Phase 1 (9,450 to 9,550 Bench) was determined to be in compliance with the approved specifications. The Certification is accepted by the Division pursuant to Rule 7.3.2 of the Mineral Rules and Regulations of The Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E.
Environmental Protection Specialist

ec: Wally Erickson, DRMS
Amy Eschberger, DRMS
Elliott Russell, DRMS
Meg Burt, CC&V
Chris Hanks, CC&V
DRMS file

