

Department of Natural Resources

1313 Sherman St. Room 215 Denver, CO 80203

December 31, 2015

Jason Burkey Oldcastle SW Group, Inc. dba United Companies of Mesa County P.O. Box 3609 Grand Junction, CO 81502-3609

## Craig Ranch Pit, Permit M-1986-002, Annual Fee Invoice and Report Request

## PLEASE READ CAREFULLY – ACTION REQUIRED Please attach your COMPLETED written Annual Report and Annual Report Map to this form

Under the terms of your Reclamation Permit and Colorado Statutes, you must submit an Annual Fee and Annual Report (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

The Annual Report and Fee requirement will be considered submitted when we have received the following components:

- 1. APPROPRIATE ANNUAL FEE
- 2. COMPLETED ANNUAL REPORT
- 3. ASSOCIATED MAP as required by rule

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the \$323.00 fee is due for the following:

Permit: M-1986-002
Operation Name: Craig Ranch Pit
Anniversary Date: February 26, 2016

Total Fee Due: \$323.00 (Due on or before your Anniversary Date)

Return the enclosed <u>Annual Report FORM</u>, a <u>MAP</u>, and a <u>CHECK</u> or <u>MONEY ORDER</u> made payable to: Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. If your records indicate these documents and fees have already been submitted, please notify the Division.



If you have additional comments and/or information that should be provided to the Division, please provide it below or attach it to this form along with your written report and map. Annual Report instructions are enclosed. If you have any questions, please feel free to contact Scottie Tate ((303) 866-3567 ext 8166) or Michelle Ramirez ((303) 866-3567 ext 8114). Thank you for your cooperation in this matter.

IF THE ANNUAL FEE SUBMITTALS ARE NOT RECEIVED ON OR BEFORE YOUR ANNIVERSARY DATE, THE ENFORCEMENT PROCESS WILL AUTOMATICALLY BE INITIATED. ENFORCEMENT ACTIONS MAY RESULT IN CIVIL PENALTIES AND/OR REVOCATION OF YOUR PERMIT.

## 112c Annual Report

	Permit Number:	M-1986-002
	Permittee Name:	Oldcastle SW Group, Inc. dba
		United Companies of Mesa County
	Operation Name:	Craig Ranch Pit
	County:	Mesa
	<b>Anniversary Date:</b>	February 26, 2016
	<b>Current Bond Amt:</b>	\$218,342.80
	Annual Fee Due:	\$323.00
(DRMS Office Use Only)	Permit Acreage:	8.40
	DRMS Specialist	SJM

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1.	Is the site identification sign posted in accordance with Rule 3.1.12(1)?	YES	NO			
2.	Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)?	YES	NO			
3.	Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.	YES	NO			
4.	What was the date of last excavation, processing or hauling activity at the mine?					
5.	Does the mine operate more than 180 days per year? If "NO", please review Rule 1.13 to assure that your mine is in compliance.	YES	NO			
6.	Has this mine been granted:  a) approval of TEMPORARY CESSATION Status? b) approval for INTERMITTENT OPERATION?	YES YES	NO NO			
7.	Number of acres currently affected (mining + incomplete and or unreleased reclamation):					
8.	Number of acres that were newly affected during the current report year:					
9.	Number of acres that were reclaimed during the current report year:					
10.	). Estimated new acreage to be affected in the next report year:					
11.	. Estimated acres to be reclaimed in the next report year:					

12. **Total acres** in various stages of reclamation, since permitted mining activities began:

Total acres	Total	acres		Total acres		Total a	cres		
backfilled:	seede			w/topsoil		mulche			
		ved mix:		replaced:			ed mulch		
Total acres	Total			Topsoil			application	on	
graded:		zed w/		replacement		rate (to	ons/ac):		
	apvd	fertilizer:		depth (in.):					
Seed		Fertilize			Mulcl	1			
application		applicat	ion		applic	ation			
method:		method:			metho				
3. Is weed control b	eing conducted	n accordance	with an	approved Weed (	Control Pla	ın?	YES	NO	N/A
If "YES", indicate	te the weed speci	es, control a	ea, contro	ol type, application	on rate and	treatme	nt date or	the rep	ort ma
. Is adequate topso	oil reserved for re	clamation b	ased on v	our approved per	mit?		YES	NO	N/A
If "NO", please 6		Ciamation, o	asca on j	our approved per			125	110	1 1/1 1
ii ivo , pieuse e	mpium.								
5. Is the reserved to	onsoil vegetated/s	tabilized in a	ccordanc	e with Rule 3.1.9	(1)?		YES	NO	N/A
If "NO" please e					(-).				
r	<b>F</b>								
6. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the Sta									
Engineer (Well F						0 1	YES	NO	N/A
7. Are all hazardous materials stored within approved spill containment structures? YES NO N/A									
8. Is your financial warranty value sufficient to cover the cost to complete reclamation? YES NO N/A									
9. Is your basis for	legal right to ent	er still valid?					YES	NO	
0. Does your permi			_	•			YES	NO	N/A
If "Yes", please a	attach the require	d monitoring	g results to	o this Annual Rep	ort.				
1 As magnined by	Colorado Minad	and Paclar	nation Ac	t and/or Colorado	Land Da	alamatio	n A at for	tha Ev	tmontic

21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14. UPDATED

MAP ATTA	CHED:	

Division records indicate the following permittee contact information. If this information is not current, please type or print **current** contact information:

Permittee Contact:	Jason Burkey	
Permittee Company:	Oldcastle SW Group, Inc. dba	
	United Companies of Mesa	
	County	
Address:	P.O. Box 3609	
	Grand Junction, CO 81502-	
	3609	
Phone Number:	(970) 243-4900	
F N 1		
Fax Number:		
Email Address:	Jburkey@oldcastlematerials.com	
I, the undersigned, hereb	y state that the information provided	in this report is true and accurate, and that site operations are
being conducted in accor	rdance with the Division approved m	ining and reclamation plans.
C::44	C	Determination of the second of
Signature of <u>Permittee,</u>	Corporate Officer, Owner, or Doc	cumented Designee Date

M-AF-01