

July 18, 2016

Wayne Brantley  
Pioneer Sand Company  
PO Box 7650  
Colorado Springs, CO 80933



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

***RE: Rock Pit Mine, Permit No. M-1985-082, Inspection Problem Abated***

Dear Mr. Brantley:

On May 10, 2016 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs and Markers was cited as a problem in the inspection report for having a sign with the incorrect mine name posted. Corrective actions required that the operator post a sign at the mine entrance that meets Rule 3.1.12(1). Specifically having the correct mine name displayed. The operator shall supply photo documentation that the updated sign was posted by the corrective action date.

On July 15, 2016 the Division received photo documentation via email that a new and correct sign had been posted at the site. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me. Amy Yeldell, at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

Sincerely,

**Amy Yeldell**

Environmental Protection Specialist  
Department of Natural Resources  
Division of Reclamation, Mining and Safety  
Phone: (970) 254-8511  
Fax: (970) 241-1516

Ec: Russ Means, Senior EPS, Grand Junction DRMS

