



Hello Mrs. Yeldell,

You see from the attached pictures the mitigation for the sediment basin has been completed with Rip-Rap Lining and Spillway and lined channel for approximately 75 feet and then soil pock marks the remaining distance.



Downhill Side View of spillway and lined channel





View of Rip Rap lining of Sediment basin





Side View of Soil Pock Marking





Downhill looking up at Soil Pock marking and Rip Rap Channel lining.