



RECEIVED

JUL 25 2016

**DIVISION OF RECLAMATION
MINING AND SAFETY**

July 25, 2016

Colorado Division of Reclamation, Mining, and Safety
Ms. Amy Eschberger
Environmental Protection Specialist
1313 Sherman Street, Room 215
Denver, CO 80203

Re: M-1984-076 DDD Mine, Elbert County, Colorado
Corrective Action Completion

Dear Ms. Eschberger:

General Shale Brick, Inc. (GSB) has received your inspection report dated October 15, 2014 for the DDD Mine. The inspection report requests that we bring the site into compliance with Colorado groundwater rules by filing for a well permit from the State Engineer Office (SEO) or backfill the mine. There is water in the east and west mines that have been there for several years.

GSB has backfilled the pit at the Western pit location (DWR) during the week of July 18, 2016.



Please feel free to contact me with any questions at 303-783-3058 or by email at jason.mcgraw@generalshale.com.

Sincerely,
General Shale Brick, Inc.

Jason E. McGraw P.E.
Mine Supervisor

RECEIVED

JUL 25 2016

**DIVISION OF RECLAMATION
MINING AND SAFETY**