

GUNNISON COUNTY, COLORADO
PUBLIC WORKS DEPARTMENT
195 BASIN PARK DRIVE
GUNNISON, CO 81230

MEMORANDUM

RECEIVED

OCT 20 2016
GRAND JUNCTION FIELD OFFICE
DIVISION OF
RECLAMATION MINING & SAFETY

TO: Dustin Czapla
Division of Reclamation, Mining and Safety

FROM: Marlene D. Crosby

DATE: October 13, 2016

SUBJECT: Taramarcaz Pit, #M-1985-072

COMMENT:

Mr. Czapla,

Enclosed please find pictures of the mine identification sign recently posted at the Taramarcaz Pit.

Please let us know if anything further needs to be completed.


**COLORADO**Division of Reclamation,
Mining and Safety

Department of Natural Resources

MINERALS PROGRAM INSPECTION REPORT**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Tamarcaz Pit	MINE/PROSPECTING ID#: M-1985-072	MINERAL: Sand and gravel	COUNTY: Gunnison
INSPECTION TYPE: Monitoring	INSPECTOR(S): Dustin M. Czapla	INSP. DATE: September 14, 2016	INSP. TIME: 17:00
OPERATOR: Gunnison County	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 110c - Construction Limited Impact	

REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: No Bond Held
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: September 19, 2016


The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

1. INSPECTION TOPIC: Signs & Markers

PROBLEM/POSSIBLE VIOLATION: Problem: The mine identification sign was not posted at the entrance of the mine site. This is a problem for failure to post a mine identification sign as required by Section 3.1.12(1) of the rule.

CORRECTIVE ACTIONS: The operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road with the following: the name of the operator, a statement that a reclamation permit for the operation has been issued by the Colorado Mined Land Reclamation Board; and the permit number. The operator shall submit photo documentation that a proper sign has been posted by the corrective action date.

CORRECTIVE ACTION DUE DATE: 10/19/16

A photograph of a gravel pit in a desert landscape. In the foreground, a sign is attached to a fence made of black metal posts and barbed wire. The sign is white with black text. The background shows a vast, arid landscape with reddish-brown soil, sparse vegetation, and distant mountains under a clear blue sky.

GUNNISON COUNTY
TARAMARCAZ
GRAVEL PIT
M - 1985 - 072



