

January 19, 2017

James Cooley
J and K Limestone Products, LLC
4469 CR 108
Mosca, CO 81146



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

RE: J and K Limestone Products – Villa Grove Pit, Permit No. M-2000-116, Inspection Problem Abated

Dear Mr. Cooley:

On August 9, 2016 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Excessive waste was cited as a problem for the presence of trash and refuse on site. Corrective actions required that you submit written notice to the Division with photo documentation that the trash has been removed from the site by the corrective action date.

On January 19, 2017 the Division received the above mentioned documentation. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me. Amy Yeldell, at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

Sincerely,

Amy Yeldell

Environmental Protection Specialist
Department of Natural Resources
Division of Reclamation, Mining and Safety
Phone: (970) 254-8511
Fax: (970) 241-1516

Ec:
Russ Means, Senior EPS, Grand Junction DRMS

