

**STATE OF
COLORADO****Ebert - DNR, Jared** <jared.ebert@state.co.us>

DeLorme Map Image

Schumacher, Jeff <Jeff.Schumacher@premieraca.com>

Mon, Jan 23, 2017 at 10:58 AM

To: "Ebert - DNR, Jared" <jared.ebert@state.co.us>

The boundary of the pit is now clearly marked. I hired Leibert - McAtee & Associates, a local surveying firm, to go out and find the proper boundary based on GPS and feet measurements. At each corner of the boundary and the mid-point on the North boundary, they placed a pin at ground level and then drove a steel fence post beside each marker. So, there are 8 steel post with at least the top foot painted orange marking the boundary of the pit. This spring, when the ground thaws, I plan to replace the steel fence post with a more permanent post that cows will not knock over, as I believe that is what happened to the original markers. This should fulfill the requirements outlined in your inspection report.

Thanks,

Jeff Schumacher

(970) 520-5683

From: Ebert - DNR, Jared [mailto:jared.ebert@state.co.us]

Sent: Wednesday, January 18, 2017 3:57 PM

To: Schumacher, Jeff

Subject: Re: DeLorme Map Image

[Quoted text hidden]

[Quoted text hidden]