



STATE OF
COLORADO

Cunningham - DNR, Michael <michaela.cunningham@state.co.us>

COMPLAINT- Katuska Pit M1991037

rrindsig@mchsi.com <rrindsig@mchsi.com>

Sat, Apr 22, 2017 at 7:05 AM

To: "Cunningham - DNR, Michael" <michaela.cunningham@state.co.us>

Cc: John Deagan <jdeagan@parkco.us>

Mr. Cunningham,

The operator of the Katuska Pit, M1991037, continues mining activities outside of the boundary of the permitted area.

The attached photographs, taken April 21, 2017, clearly show only some of the activity.

In the photos one can see an office or storage trailer, a yellow tent, portable toilets, large truck, articulated loader, and excavator that are indisputably outside the permitted boundary.

These items have been recently moved into the area (they are not seen in the DRMS inspection photos from December 5, 2016).

Also visible is a large tracked mobile feeder/conveyor, which may or may not be outside the boundary.

Not visible, but hidden by trees, are several vehicles, UTV's, smaller items of equipment, etc. that are outside the permitted boundary.

Per our previous conversations, this activity is not permitted, and constitutes mining without a permit. (it is also illegal mining activity in a residential zoned area)

I trust you will immediately look into this matter.

Regards,

Robin Rindsig

Katuska today photos.zip
2496K













