

June 8, 2017

Stacy Quick
Cross Mountain Ranch Ltd. Partnership
P.O. Box 897
Craig, CO 81626



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

RE: Kagie Gravel Pit, Permit No. M-1979-102, Inspection Problem Abated

Dear Ms. Quick:

On August 17, 2016 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs and markers was cited as a problem because several markers were missing or misplaced. Corrective actions required the operator conduct a survey and replace the boundary markers in the correct location(s) and submit photo document proof by the corrective action date.

On June 8, 2017 the Division received a letter containing several photos depicting markers delineating the permit boundary and a statement that the site was re-surveyed. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me. Amy Yeldell, at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

Sincerely,

Amy Yeldell

Environmental Protection Specialist
Department of Natural Resources
Division of Reclamation, Mining and Safety
Phone: (970) 254-8511
Fax: (970) 241-1516

Ec:
Russ Means, Senior EPS, Grand Junction DRMS

