



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman St. Room 215
Denver, CO 80203

September 11, 2017

Ralph Bell
Castle Rock Construction Company of Colorado, LLC
6374 S. Racine Circle
Centennial, CO 80111

**Re: Vick Borrow Pit, Permit No. M-2010-048;
Financial Warranty Release Denial, Revision No. SL-1**

Ralph Bell:

On September 11, 2017 the Division of Reclamation, Mining and Safety considered your request for a financial warranty release. The Division found that reclamation had not been accomplished at this site and denied this request. Please review the attached inspection report for the specific reasons for the financial warranty release denial. In addition, if you have past due annual fees or unpaid civil penalties, your financial warranty cannot be released.

If you have any questions, please contact me.

Sincerely,

Timothy A. Cazier, P.E.
Environmental Protection Specialist

Enclosure: Inspection Report

Cc: DRMS file

M-FW-12

