

Musick - DNR, Jason <jason.musick@state.co.us>

Deserado Mine, C-1981-08, 3rd Quarter 2017 DMR, Sediment Pond and Subsidence Inspection Reports Review Letter

1 message

Musick - DNR, Jason <jason.musick@state.co.us> To: Scott Wanstedt <swanstedt@deserado.com> Mon, Dec 4, 2017 at 8:44 AM

Good morning Scott,

Attached is the Division's review of the above referenced reports associated with the Deserado Mine.

Please let me know if you have any questions or comments.

Thanks, Jason

Jason Musick Environmental Protection Specialist III Coal Regulatory Program



COLORADO

Division of Reclamation, Mining and Safety Department of Natural Resources

P 303.866.3567 x 8134 | F 303.832.8106 1313 Sherman Street, Room 215, Denver, CO 80203 jason.musick@state.co.us | http://mining.state.co.us

2 attachments

3Q17_DMR.pdf 123K

3Q17_Pond.pdf 129K



COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

1313 Sherman Street, Room 215 Denver, CO 80203

December 4, 2017

Scott Wanstedt Blue Mountain Energy, Inc. 3607 County Road #65 Rangely, CO 81648

RE: Blue Mountain Energy, Inc. Deserado Mine, Permit C-1981-018 Third Quarter 2017 Discharge Monitoring Report Review

Dear Mr. Wanstedt:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with Rule 4.05.13(2). The Third Quarter 2017 Discharge Monitoring Report for the above referenced CDPS Permit was received by the Division on 31 October 2017; the reports cover the time period from 01 July 2017 through 30 September 2017.

During the third quarter of 2017 only outfalls 045-A, discharged.

No exceedances were noted.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

int

Jason Musick Environmental Protection Specialist Jason.musick@state.co.us





COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

1313 Sherman Street, Room 215 Denver, CO 80203

December 4, 2017

Scott Wanstedt Blue Mountain Energy, Inc. 3607 County Road #65 Rangely, CO 81648

RE: Blue Mountain Energy, Inc. Deserado Mine, Permit C-1981-018 Third Quarter 2017 Pond Inspection Report Review Third Quarter 2017 County Road #65 Subsidence Report Review

Dear Mr. Wanstedt:

Third Quarter 2017 Pond Inspection Report Review

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with the following CDRMS regulation(s):

4.05.9(17) - Examined at least quarterly by a qualified person designated by the operator, for appearance of structural weakness and other hazardous conditions.

4.05.9(17) - A copy of the report shall be submitted to the Division on a quarterly basis.

The third quarter pond inspection report was received by the Division on October 31, 2017. Pond inspections were conducted by Scott Wanstedt of BME on September 28, 2017.

It is noted that discharge was only observed from the B-Seam dewatering pond #5. The Division understands that, based on the information in the report, seepage at the BD2-5 dewatering pond was observed. This area is being monitored to ensure that the integrity of the pond is not comprimised.

Third Quarter 2017 County Road #65 Subsidence Report Review

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) have found the above referenced report to be in compliance with the requirements of C-1981-081 unless noted below.

Longwall mining did not occur under RCR #65 during the quarter. Only superficial surface impacts from prior mining was observed and no significant damage that would warrant repairs. These observations



Blue Mountain Energy, Inc Page 2 12/4/2017

reflect the Division's observations during the on-the-ground inspections conducted during the third quarter 2017.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

mit las

Jason Musick Environmental Protection Specialist