



NOTES:
-The entire acreage of the site has been disturbed, with the exception of some native vegetation remaining along the fencelines and property boundaries
-Topsoil is in place along roads and banks, not stockpiled
-Some reclamation work to be performed in North Cell in 2018

South Platte River

Worthing property
16.37 acres
backfilled in 2017

Area of material
that may be mined,
once pump house
location is moved

Mining permit boundary

French Drain
(Underground)

Pit floor and reservoir
side walls, to be below
water level, reclaimed
during 2017
(Approximately 60 acres)

South Cell
Reservoir

15 acres
seeded and
hydromulched
March 2016

Approximately
53.22 acres covered
in reservoir water

Approximately 68.22
acres total



TITLE
Brannan Sand and Gravel Company, LLC
Pit 29
2016 Mining Annual Report
Colorado Division of Reclamation, Mining and Safety
Permit M1980-183

SIZE	CAGE CODE	DWG NO	REV
SCALE	1"=500'		SHEET 1 of 1